

# M400/2XH Type 1

## Multi-Parameter Transmitter



**METTLER TOLEDO**

ISM is a trademark of the METTLER TOLEDO Group.

All other trademarks are the property of their respective holders.

## Content

<b>1</b>	<b>Introduction</b>	<b>7</b>
<b>2</b>	<b>Safety Instructions</b>	<b>8</b>
2.1	Definition of Equipment and Documentation Symbols and Designations	8
2.2	Correct Disposal of the Unit	9
2.3	Ex Instructions for M400 Series Multi-parameter Transmitters – ATEX, IECEx	10
2.4	Ex Instructions for M400 Series Multi-parameter Transmitters – FM Approval	12
2.4.1	Instructions of Use to be Considered under FM Approval	12
2.4.1.1	General Notes	14
2.4.1.2	Cautionary Notes, Warnings and Markings	14
2.4.1.3	Control Drawings	16
<b>3</b>	<b>Unit Overview</b>	<b>17</b>
3.1	Overview ½ DIN	17
3.2	Control/Navigation Keys	18
3.2.1	Menu Structure	18
3.2.2	Navigation Keys	18
3.2.2.1	Navigating the Menu Tree	18
3.2.2.2	Escape	19
3.2.2.3	ENTER	19
3.2.2.4	Menu	19
3.2.2.5	Calibration Mode	19
3.2.2.6	Info Mode	19
3.2.3	Navigation of Data Entry Fields	19
3.2.4	Entry of Data Values, Selection of Data Entry Options	19
3.2.5	Navigation with ↑ in Display	20
3.2.6	"Save Changes" Dialog	20
3.2.7	Security Passwords	20
3.2.8	Display	20
<b>4</b>	<b>Installation Instruction</b>	<b>21</b>
4.1	Unpacking and Inspection of Equipment	21
4.1.1	Panel Cutout Dimensional Information – ½ DIN Models	21
4.1.2	Installation Procedure	22
4.1.3	Assembly – ½ DIN Version	22
4.1.4	½ DIN Version – Dimension Drawings	23
4.1.5	½ DIN Version – Pipe-Mounting	23
4.2	Connection of Power Supply	24
4.2.1	Housing (Wall-Mounting)	24
4.3	Terminal Block (TB) Definitions	25
4.4	Terminal Block TB1	25
4.5	Terminal Block TB2: Analog Sensors	26
4.5.1	Conductivity <b>4-e</b> Analog Sensors	26
4.5.2	pH and Redox (ORP) Analog Sensors	26
4.6	Terminal Block TB2: ISM Sensors	27
4.6.1	pH ISM Sensors	27
4.7	Connection of ISM Sensors	28
4.7.1	Connection of ISM Sensors for pH/ORP	28
4.7.2	TB2 – AK9 Cable Assignment	28
4.8	Connection of Analog Sensors	29
4.8.1	Connection of Analog Sensor for pH/ORP	29
4.8.2	TB2 – Typical Wiring for Analog pH/ORP Sensor	30
4.8.2.1	Example 1	30
4.8.2.2	Example 2	31
4.8.2.3	Example 3	32
4.8.2.4	Example 4	33
<b>5</b>	<b>Placing Transmitter in or out of Service</b>	<b>34</b>
5.1	Placing Transmitter in Service	34
5.2	Placing Transmitter out of Service	34

<b>6</b>	<b>Quick Setup</b>	<b>35</b>
<b>7</b>	<b>Sensor Calibration</b>	<b>36</b>
7.1	Enter Calibration Mode	36
7.1.1	Select the Desired Sensor Calibration Task	36
7.1.2	Finish Calibration	37
7.2	Conductivity Calibration for Four-Electrode Sensors	38
7.2.1	One-Point Sensor Calibration	38
7.2.2	Two-Point Sensor Calibration	39
7.2.3	Process Calibration	40
7.3	pH Calibration	41
7.3.1	One-Point Calibration	41
7.3.1.1	Auto Mode	41
7.3.1.2	Manual Mode	42
7.3.2	Two-Point Calibration	42
7.3.2.1	Auto Mode	42
7.3.2.2	Manual Mode	43
7.3.3	Process Calibration	43
7.3.4	mV Calibration (only for analog sensors)	44
7.3.5	ORP Calibration (only for ISM sensors)	44
7.4	Sensor Temperature Calibration (only for analog sensors)	45
7.4.1	One-Point Sensor Temperature Calibration	45
7.4.2	Two-Point Sensor Temperature Calibration	45
7.5	Edit Sensor Calibration Constants (only for analog sensor)	46
7.6	Sensor Verification	46
<b>8</b>	<b>Configuration</b>	<b>47</b>
8.1	Enter Configuration Mode	47
8.2	Measurement	47
8.2.1	Channel Setup	47
8.2.1.1	Analog Sensor	48
8.2.1.2	ISM Sensor	48
8.2.1.3	Save Changes of the Channel Setup	49
8.2.2	Temperature Source (only for analog sensors)	49
8.2.3	Parameter-related Settings	49
8.2.3.1	Conductivity Temperature Compensation	50
8.2.3.2	Concentration Table	51
8.2.3.3	pH/ORP Parameters	52
8.2.4	Set Averaging	53
8.3	Analog Outputs	53
8.4	Set Points	54
8.5	Alarm/Clean	56
8.5.1	Alarm	56
8.5.2	Clean	57
8.6	ISM Set Up (available for pH ISM sensors)	58
8.6.1	Sensor Monitoring	58
8.6.2	Reset ISM Counter/Timer	59
8.6.3	DLI Stress Adjustment (only for pH ISM sensors)	60
8.7	Display	60
8.7.1	Measurement	60
8.7.2	Resolution	61
8.7.3	Backlight	61
8.7.4	Name	61
8.7.5	ISM Sensor Monitoring (available when ISM sensor connected)	62
8.8	Hold Analog Outputs	62

<b>9</b>	<b>System</b>	<b>63</b>
9.1	Set Language	63
9.2	Passwords	63
	9.2.1 Changing Passwords	64
	9.2.2 Configuring Menu Access for Operator	64
9.3	Set/Clear Lockout	64
9.4	Reset	64
	9.4.1 Reset System	65
	9.4.2 Reset Meter Calibration	65
	9.4.3 Reset Analog Calibration	65
9.5	Set Date & Time	65
<b>10</b>	<b>Service</b>	<b>66</b>
10.1	Diagnostics	66
	10.1.1 Model/Software Revision	66
	10.1.2 Digital Input	66
	10.1.3 Display	67
	10.1.4 Keypad	67
	10.1.5 Memory	67
	10.1.6 Set OC	67
	10.1.7 Read OC	68
	10.1.8 Set Analog Outputs	68
	10.1.9 Read Analog Outputs	68
10.2	Calibrate	68
	10.2.1 Calibrate Meter (only for channel A)	69
	10.2.1.1 Temperature	69
	10.2.1.2 Current	69
	10.2.1.3 Voltage	70
	10.2.1.4 Rg Diagnostic	70
	10.2.1.5 Rr Diagnostic	71
	10.2.1.6 Calibrate Analog Output Signals	71
	10.2.2 Calibrate Unlock	72
10.3	Tech Service	72
<b>11</b>	<b>Info</b>	<b>73</b>
11.1	Messages	73
11.2	Calibration Data	73
11.3	Model/Software Revision	74
11.4	ISM Sensor Info (available when ISM sensor connected)	74
11.5	ISM Sensor Diagnostics (available when ISM sensor connected)	74
<b>12</b>	<b>Maintenance</b>	<b>77</b>
12.1	Front Panel Cleaning	77
<b>13</b>	<b>Troubleshooting</b>	<b>78</b>
13.1	Cond (resistive) Error Messages/ Warning- and Alarm List for Analog Sensors	78
13.2	pH Error Messages/Warning- and Alarm List	79
	13.2.1 pH Sensors except Dual Membrane pH Electrodes	79
	13.2.2 Dual Membrane pH Electrodes (pH/pNa)	80
	13.2.3 ORP Messages	80
13.3	Warning- and Alarm Indication on the Display	81
	13.3.1 Warning Indication	81
	13.3.2 Alarm Indication	81
<b>14</b>	<b>Accessories and Spare Parts</b>	<b>82</b>
<b>15</b>	<b>Specifications</b>	<b>83</b>
15.1	General Specifications	83
15.2	Electrical Specifications	85
	15.2.1 General Electrical Specifications	85
	15.2.2 4 to 20 mA (with HART)	85
15.3	Mechanical Specifications	85
15.4	Environmental Specifications	86
15.5	Control Drawings	87
	15.5.1 Installation, Maintenance and Inspection	87
	15.5.2 Control Installation Drawing General Installation	88
	15.5.3 Notes	91

---

<b>16</b>	<b>Default Table</b>	<b>92</b>
<b>17</b>	<b>Warranty</b>	<b>96</b>
<b>18</b>	<b>Buffer Tables</b>	<b>97</b>
18.1	Standard pH Buffers	97
18.1.1	Mettler-9	97
18.1.2	Mettler-10	98
18.1.3	NIST Technical Buffers	98
18.1.4	NIST Standard Buffers (DIN and JIS 19266: 2000-01)	99
18.1.5	Hach Buffers	99
18.1.6	Ciba (94) Buffers	100
18.1.7	Merck Titrisole, Riedel-de-Haën Fixanale	100
18.1.8	WTW Buffers	101
18.1.9	JIS Z 8802 Buffers	101
18.2	Dual Membrane pH Electrode Buffers	102
18.2.1	Mettler-pH/pNa Buffers (Na <sup>+</sup> 3.9M)	102

# 1 Introduction

Statement of Intended Use – The 2-wire M400 multi-parameter transmitter is a single-channel online process instrument with HART™ communication capabilities for measuring various properties of fluids and gases. These include pH/ORP, pH/pNa and conductivity.

The M400/2XH Type 1 is a mixed mode transmitter that can handle conventional sensors (analog) or ISM sensors (digital).

## M400/2XH Type 1 parameter fit guide

Parameter	M400/2XH Type 1	
	Analog	ISM
pH/ORP	•*	•*
pH/pNa	–	•
Conductivity 2-e	•**	–
Conductivity 4-e	•	–
Amp. Dissolved Oxygen ppm / ppb / trace	-/-/-	-/-/-
Amp. Oxygen gas	–	–
Optical Dissolved Oxygen ppm / ppb	-/-	-/-
Dissolved Carbon Dioxide (CO <sub>2</sub> low)	–	–

\* Excluding InPro 3100 (i), InPro 3300 and InPro 3253(i)

\*\* Available from software version V\_1.0.02

A large four line backlit Liquid Crystal Display conveys measuring data and setup information. The menu structure allows the operator to modify all operational parameters by using keys on the front panel. A menu-lockout feature, with password protection, is available to prevent the unauthorized use of the meter. The M400 multi-parameter transmitter can be configured to use its two analog and/or two open collector (OC) outputs for process control.

This description corresponds to the firmware release. Upgrades are implemented without prior notification.

## 2 Safety Instructions

This manual includes safety information with the following designations and formats.

### 2.1 Definition of Equipment and Documentation Symbols and Designations



**WARNING:** POTENTIAL FOR PERSONAL INJURY.



**CAUTION:** possible instrument damage or malfunction.



**NOTE:** Important operating information.



On the transmitter or in this manual text indicates: Caution and/or other possible hazard including risk of electric shock (refer to accompanying documents)

The following is a list of general safety instructions and warnings. Failure to adhere to these instructions can result in damage to the equipment and/or personal injury to the operator.

- The M400 Transmitter should be installed and operated only by personnel familiar with the transmitter and who are qualified for such work.
- The M400 Transmitter must be operated only under the specified operating conditions (see section 16 "Specifications").
- Repair of the M400 Transmitter must be performed by authorized, trained personnel only.
- With the exception of routine maintenance, cleaning procedures or fuse replacement, as described in this manual, the M400 Transmitter must not be tampered with or altered in any manner.
- METTLER TOLEDO accepts no responsibility for damage caused by unauthorized modifications to the transmitter.
- Follow all warnings, cautions and instructions indicated on and supplied with this product.
- Install equipment as specified in this instruction manual. Follow appropriate local and national codes.
- Protective covers must be in place at all times during normal operation.
- If this equipment is used in a manner not specified by the manufacturer, the protection provided by it against hazards may be impaired.



**WARNINGS:**

Installation of cable connections and servicing of this product require access to shock hazard voltage levels.

Main power and OC contacts wired to separate power sources must be disconnected before servicing.

Switch or circuit breaker shall be in close proximity to the equipment and within easy reach of the OPERATOR; it shall be marked as the disconnecting device for the equipment. Main power must employ a switch or circuit breaker as the disconnecting device for the equipment.

All electrical installations must be in accordance with the National Electrical Code and/or any other applicable national or local codes.



**NOTE: PROCESS UPSETS**

Because process and safety conditions may depend on consistent operation of this transmitter, provide appropriate means to maintain operations during sensor cleaning or replacement, or sensor or instrument calibration.



**NOTE:** This is a 2-wire-product with two active 4–20 mA analog output.

## 2.2 Correct Disposal of the Unit

When the transmitter is finally removed from service, observe all local environmental regulations for proper disposal.

## 2.3 Ex Instructions for M400 Series Multi-parameter Transmitters – ATEX, IECEx

M400 series multi-parameter transmitters are produced by Mettler-Toledo GmbH. They have passed the inspection of IECEx and conform to the following standards:

- **IEC 60079-0 : 2017**  
**Edition: 7.0 Explosive atmospheres –**  
**Part 0: General requirements**
- **IEC 60079-11 : 2011**  
**Edition: 6.0 Explosive atmospheres –**  
**Part 11: Equipment protection by intrinsic safety “i”**

**Ex Marking:**

- **Ex ib [ia Ga] IIC T4 Gb**
- **Ex ib [ia Da] IIIC T80°C Db IP66**

**Certificate No.:**

- **IECEx NEP 18.0007X**
- **SEV 12 ATEX 0132 X**


**1. Special Conditions of use (X-marking in the Certificate Number):**

1. Avoid ignition hazard due to impact or friction, prevent mechanical sparks.
2. Avoid electrostatic discharge on enclosure surface, use wet cloth only for cleaning.
3. In hazardous area, IP66 cable glands (as supplied) must be mounted.

**2. Pay particular attention to the following when using the transmitter:**

1. Rated ambient temperature range:
  - for gas atmosphere:  $-20 \sim +60$  °C
  - for dust atmosphere:  $-20 \sim +57$  °C
2. No operation on the upgrade interface in hazardous area.
3. Users shall not arbitrarily replace the internal electrical components.
4. When installation, use and maintenance, IEC 60079-14 should be observed.
5. When installation in explosive dust atmosphere
  - 5.1 Cable gland or blanking plug to IEC 60079-0:2011 and IEC 60079-11:2011 with marking Ex ia IIIC IP66 should be adopted.
  - 5.2 The overlay switch of multi-parameter transmitter shall be protected from light.
  - 5.3 Avoid high risk of mechanical danger on the overlay switch.
6. Observe the warning: potential electrostatic charging hazard - see instructions, avoid ignition hazard due to impact or friction for Ga application.
7. For connection to intrinsically safe circuits, use the maximum values in the following table.

Terminal	Function	Safety Parameters				
10, 11	Aout1	$U_i = 30 \text{ V}$	$I_i = 100 \text{ mA}$	$P_i = 0.8 \text{ W}$	$L_i \approx 0$	$C_i = 15 \text{ nF}$
12, 13	Aout2	$U_i = 30 \text{ V}$	$I_i = 100 \text{ mA}$	$P_i = 0.8 \text{ W}$	$L_i \approx 0$	$C_i = 15 \text{ nF}$
1, 2; 3, 4;	Digital Input	$U_i = 30 \text{ V}$	$I_i = 100 \text{ mA}$	$P_i = 0.8 \text{ W}$	$L_i \approx 0$	$C_i \approx 0$
6, 7; 8, 9;	OC Output	$U_i = 30 \text{ V}$	$I_i = 100 \text{ mA}$	$P_i = 0.8 \text{ W}$	$L_i \approx 0$	$C_i \approx 0$
P,Q	Analog Input	$U_i = 30 \text{ V}$	$I_i = 100 \text{ mA}$	$P_i = 0.8 \text{ W}$	$L_i \approx 0$	$C_i = 15 \text{ nF}$
N, O	RS485 Sensor	$U_i = 30 \text{ V}$ $U_o = 5.88 \text{ V}$	$I_i = 100 \text{ mA}$ $I_o = 54 \text{ mA}$	$P_i = 0.8 \text{ W}$ $P_o = 80 \text{ mW}$	$L_i \approx 0$ $L_o = 1 \text{ mH}$	$C_i = 0.7 \text{ }\mu\text{F}$ $C_o = 1.9 \text{ }\mu\text{F}$
A, E, G	pH Sensor	$U_o = 5.88 \text{ V}$	$I_o = 1.3 \text{ mA}$	$P_o = 1.9 \text{ mW}$	$L_o = 5 \text{ mH}$	$C_o = 2.1 \text{ }\mu\text{F}$
B, A, E, G	Conductivity Sensor	$U_o = 5.88 \text{ V}$	$I_o = 29 \text{ mA}$	$P_o = 43 \text{ mW}$	$L_o = 1 \text{ mH}$	$C_o = 2.5 \text{ }\mu\text{F}$
K, J, I	Temperature Sensor	$U_o = 5.88 \text{ V}$	$I_o = 5.4 \text{ mA}$	$P_o = 8 \text{ mW}$	$L_o = 5 \text{ mH}$	$C_o = 2 \text{ }\mu\text{F}$
H, B, D	Dissolved Oxygen sensor	$U_o = 5.88 \text{ V}$	$I_o = 29 \text{ mA}$	$P_o = 43 \text{ mW}$	$L_o = 1 \text{ mH}$	$C_o = 2.5 \text{ }\mu\text{F}$
L	One-wire Sensor	$U_o = 5.88 \text{ V}$	$I_o = 22 \text{ mA}$	$P_o = 32 \text{ mW}$	$L_o = 1 \text{ mH}$	$C_o = 2.8 \text{ }\mu\text{F}$



Label Model M400/2XH Type 1

## 2.4 Ex Instructions for M400 Series Multi-parameter Transmitters – FM Approval

### 2.4.1 Instructions of Use to be Considered under FM Approval



M400 series multi-parameter transmitters are produced by Mettler-Toledo GmbH. It has passed the inspection of NRTL cFMus and conforms to the following requirements:

The equipment is provided with an internal bond wiring and an internal flying lead wire for grounding purposes.

<b>US marking</b>	
Operating temperature range	–20 °C to +60 °C (–4 °F to +140 °F)
Environmental designation	Enclosure type 4X, IP 66
Intrinsically safe	– Class I, Division 1, Groups A, B, C, D T4A – Class II, Division 1, Groups E, F, G – Class III
Intrinsically safe	Class I, Zone 0, AEx ia IIC T4 Ga
Parameters	– Entity: Control drawing 12112601 and 12112602 – FISCO: Control drawing 12112603 and 12112602
Nonincendive	– Class I, Division 2, Groups A, B, C, D T4A – Class I, Zone 2, Groups IIC T4
Certificate no.	3046275
Standards	– FM3810:2005 Approval Standard for Electrical Equipment for Measurement, Control and Laboratory Use – ANSI/IEC-60529:2004 Degrees of Protection Provided by Enclosures (IP Codes) – ANSI/ISA-61010-1:2004 Edition: 3.0 Safety Requirements for Electrical Equipment for Measurement, Control, and Laboratory Use – Part 1: General Requirements – ANSI/NEMA 250:1991 Enclosures for Electrical Equipment (1,000 Volts Maximum) – FM3600:2011 Approval Standard for Electrical Equipment for Use in Hazardous (Classified) Locations – General Requirements – FM3610:2010 Approval Standard for Intrinsically Safe Apparatus and Associated Apparatus for Use in Class I, II & III, Division 1, Hazardous (Classified) Locations – FM3611:2004 Approval Standard for Nonincendive Electrical Equipment for Use in Class I & II, Division 2, and Class III, Division 1 & 2, Hazardous (Classified) Locations – ANSI/ISA-60079-0:2013 Edition: 6.0 Explosive Atmospheres – Part 0: General Requirements – ANSI/ISA-60079-11:2012 Edition: 6.0 Explosive Atmospheres – Part 11: Equipment Protection by Intrinsic Safety “i”

<b>Canadian marking</b>	
Operating temperature range	–20 °C to +60 °C (–4 °F to +140 °F)
Environmental designation	Enclosure type 4X, IP 66
Intrinsically safe	– Class I, Division 1, Groups A, B, C, D T4A – Class II, Division 1, Groups E, F, G – Class III
Intrinsically safe	Class I, Zone 0, Ex ia IIC T4 Ga
Parameters	– Entity: Control drawing 12112601 and 12112602 – FISCO: Control drawing 12112603 and 12112602
Nonincendive	Class I, Division 2, Groups A, B, C, D T4A
Certificate no.	3046275
Standards	– CAN/CSA-C22.2 No. 60529:2010 Degrees of Protection Provided by Enclosures (IP Codes) – CAN/CSA-C22.2 No. 61010-1:2004 Edition: 3.0 Safety Requirements for Electrical Equipment for Measurement, Control, and Laboratory Use – Part 1: General Requirements – CAN/CSA-C22.2 No. 94:1976 Special Purpose Enclosures – Industrial Products – CAN/CSA-C22.2 No. 213-M1987:2013 Non-Incendive Equipment for Use in Class I, Division 2 Hazardous Locations – Industrial Products – CAN/CSA-C22.2 No. 60079-0:2011 Edition: 2.0 Explosive Atmospheres – Part 0: General Requirements – CAN/CSA-C22.2 No. 60079-11:2014 Edition: 2.0 Explosive Atmospheres – Part 11: Equipment Protection by Intrinsic Safety “i”

### 2.4.1.1 General Notes

**NOTE:**

The Multi-parameter Transmitter M400/2XH Type 1 is suitable for use in hazardous atmospheres of all combustible materials of explosion groups A, B, C, D, E, F and G for applications requiring Class I, II, III, Division 1 instruments and groups A, B, C and D for applications requiring Class I, Division 2 instruments (National Electrical Code® (ANSI/NFPA 70 (NEC®), Article 500; or Canadian Electrical (CE) Code® (CEC Part 1, CAN/CSA-C22.1), Appendix F when installed in Canada), or of explosion groups IIC, IIB or IIA for applications requiring Class I, Zone 0, AEx/Ex ia IIC T4, Ga instruments (National Electrical Code (ANSI/NFPA 70 (NEC), Article 500; or Canadian Electrical (CE) Code (CEC Part 1, CAN/CSA-C22.1), Appendix F when installed in Canada).

If the Multi-parameter Transmitter M400/2XH Type 1 is installed and operated in hazardous areas, the general Ex installation regulations as well as these safety instructions must be observed.

The operating instructions as well as the installation regulations and standards that apply for explosion protection of electrical systems must always be observed.

The installation of explosion-endangered systems must always be carried out by qualified personnel.

For mounting instructions on specific valves refer to the mounting instructions supplied with the mounting kit. Mounting does not affect the suitability of the SVI FF positioner for use in a potentially hazardous environment.

The equipment is not intended to be used as personal protective equipment. To prevent injury, read the manual before use.

For language translation assistance, contact your local representative or email [process.service@mt.com](mailto:process.service@mt.com).

Pour la langue de traduction aide, contactez votre représentant local ou envoyez un e-mail [process.service@mt.com](mailto:process.service@mt.com).

### 2.4.1.2 Cautionary Notes, Warnings and Markings

**Hazardous location notes:**

1. For guidance on U.S. installations, see ANSI/ISA-RP12.06.01, Installation of Intrinsically Safe Systems for Hazardous (Classified) Locations.
2. Installations in the U.S. shall comply with the relevant requirements of the National Electrical Code (ANSI/NFPA 70 (NEC)).
3. Installations in Canada shall comply with the relevant requirements of the Canadian Electrical (CE) Code (CEC Part 1, CAN/CSA-C22.1).
4. Wiring methods must conform to all local and national codes governing the installation, and wiring must be rated for at least +10 °C above the highest expected ambient temperature.
5. Where the protection type allows and depends on wiring glands, the glands must be certified for the type of protection required and area classification identified on the equipment or system nameplate.
6. The internal grounding terminal shall be used as the primary equipment grounding means and the external grounding terminal is only for a supplemental (secondary) bonding connection where local authorities permit or require such a connection.

7. A dust-tight conduit seal shall be used when installed in Class II conductive and non-conductive dust environments and Class III combustible flyings environments.
8. Approved seals against ingress of water or dust are required and the NPT or metric thread fittings must be sealed with tape or thread sealant in order to meet the highest level of ingress protection.
9. When the equipment is supplied with plastic dust plugs in the conduit/cable gland entries; it is the end-user's responsibility to provide cable glands, adaptors and/or blanking plugs suitable for the environment in which the equipment is installed. When installed in a hazardous (classified) location, the cable glands, adaptors and/or blanking plugs shall additionally be suitable for the hazardous (classified) location, the product certification, and acceptable to the local authority having jurisdiction for the installation.
10. The end-user must consult the manufacturer for repair disclaimers. Only certified parts, such as entry plugs, mounting and cover lock screws and gaskets, supplied by the manufacturer are permitted. No substitutions with non-manufacturer supplied parts are permitted.
11. Tighten cover screws to 1.8 Nm (15.8 lb-in.). Overtorquing may cause enclosure breakage.
12. The minimum tightening torque for M4 (No. 6) binding screw protective conductor terminals is 1.2 Nm (10.6 lb-in.) or greater, as specified.
13. Care must be taken during installation to avoid impacts or friction that could create an ignition source.
14. Use copper, copper-clad aluminum or aluminum conductors only.
15. The recommended tightening torque for field wiring terminals is 0.8 Nm (7 lb-in.) or greater, as specified.
16. The Nonincendive version of the Multi-parameter Transmitter M400/2XH Type 1 must be connected to limited output NEC Class 2 circuits, as outlined in the National Electrical Code (ANSI/NFPA 70 (NEC)), only. If the devices are connected to a redundant power supply (two separate power supplies), both must meet this requirement.
17. The Class I, Zone 2 certifications are based on Division evaluations and the marking acceptance of Article 505 of the National Electrical Code (ANSI/NFPA 70 (NEC)).
18. The Multi-parameter Transmitter M400/2XH Type 1 assessed was certified by FM Approvals under a Type 3 Certification System as identified in ISO Guide 67.
19. Tampering and replacement with non-factory components may adversely affect the safe use of the system.
20. Insertion or withdrawal of removable electrical connectors is to be accomplished only when the area is known to be free of flammable vapors.
21. The Multi-parameter Transmitter M400/2XH Type 1 is not intended for servicing or maintenance operation. Malfunctioning units operating out of manufacturer's specification should be discarded and replaced with a new operational unit.
22. Substitution of components may impair intrinsic safety.
23. Do not open when an explosive atmosphere is present.
24. Explosion hazard, do not disconnect while circuit is live unless area is known to be non-hazardous.
25. Explosion hazard, substitution of components may impair suitability for Class I, Division 2.

Intrinsically Safe Version  
 SECURITÉ INTRINSÈQUE, Exia  
 C/US IS/1, II, III/1/ABCEFG/T4  
 US I/O/AEx ia/II/C/T4  
 C I/O/Ex ia/II/C/T4  
 Entity



Enclosure Type 4X IP66  
 -20 °C ≤ Ta ≤ +60 °C  
 Control Drawing No. 12112601  
 FM16US0216X, FM16CA0119X

Entry thread: Metric, 5xM20;  
 NOTE:

1. Conduit Hubs/Fittings Entry Thread;
2. Must use minimum Class I, Division 2, Groups A, B, C, D, Type 4X and IP66 suitable Hubs/Fittings & Cable Glands to fulfill the complete FM certification. Operation Manual No.30031683

WARNING - EXPLOSION HAZARD. DO NOT REMOVE OR REPLACE WHILE CIRCUIT IS LIVE WHEN A FLAMMABLE OR COMBUSTIBLE ATMOSPHERE IS PRESENT.  
 WARNING - POTENTIAL ELECTROSTATIC CHARGE HAZARD. USE ONLY DAMP CLOTH WHEN CLEANING OR WIPING. DO NOT USE SOLVENT.  
 AVERTISSEMENT - RISQUE D'EXPLOSION. NE PAS DÉBRANCHER TANT QUE LE CIRCUIT EST SOUS TENSION, À MOINS QU'IL NE S'AGISSE D'UN EMPLACEMENT NON DANGEREUX.

Label Model M400/2XH Type 1

### 2.4.1.3 Control Drawings


Refer to section "15.5 Control Drawings" on Page 87.




### 3 Unit Overview

The M400/2XH Type 1 is available in ½ DIN case size and provides an integral IP66/NEMA4X housing for wall- or pipe mount.

#### 3.1 Overview ½ DIN



- 1: Hard Polycarbonate Case
- 2: Five Tactile-Feedback Navigation Keys
- 3: Four-line LC Display




- 1: TB1 – Input and Output Signal
- 2: TB2 – Sensor Signal

## 3.2 Control/Navigation Keys

### 3.2.1 Menu Structure

Below is the structure of the M400 menu tree:



### 3.2.2 Navigation Keys



#### 3.2.2.1 Navigating the Menu Tree

Enter the desired main Menu branch with the ◀▶ or ▲ keys. Use the ▲ and ▼ keys to navigate through the selected Menu branch.



**NOTE:** In order to back up one menu page, without escaping to the measurement mode, move the cursor under the UP Arrow character (↑) at the bottom right of the display screen and press [ENTER].

### 3.2.2.2 Escape

Press the ◀ and ▶ key simultaneously (escape) to return to the Measurement mode.

### 3.2.2.3 ENTER

Use the ↵ key to confirm action or selections.

### 3.2.2.4 Menu

Press the ◀ key to access the main Menu.

### 3.2.2.5 Calibration Mode

Press the ▶ key to enter Calibration mode.

### 3.2.2.6 Info Mode

Press the ▼ key to enter Info mode.

## 3.2.3 Navigation of Data Entry Fields

Use the ▶ key to navigate forward or the ◀ key to navigate backwards within the changeable data entry fields of the display.

## 3.2.4 Entry of Data Values, Selection of Data Entry Options

Use the ▲ key to increase or the ▼ key to decrease a digit. Use the same keys to navigate within a selection of values or options of a data entry field.



**NOTE:** Some screens require configuring multiple values via the same data field (ex: configuring multiple setpoints). Be sure to use the ▶ or ◀ key to return to the primary field and the ▲ or ▼ key to toggle between all configuration options before entering to the next display screen.

### 3.2.5 Navigation with ↑ in Display

If a ↑ is displayed on the bottom right hand corner of the display, you can use the ► or the ◀ key to navigate to it. If you click [ENTER] you will navigate backwards through the menu (go back one screen). This can be a very useful option to move back up the menu tree without having to exit into the measuring mode and re-enter the menu.

### 3.2.6 "Save Changes" Dialog

Three options are possible for the "Save changes" dialog:

- "Yes & Exit" (Save changes and exit to measuring mode)
- "Yes & ↑" (Save changes and go back one screen)
- "No & Exit" (Don't save changes and exit to measuring mode). The "Yes & ↑" option is very useful if you want to continue configuring without having to re-enter the menu.

### 3.2.7 Security Passwords

The M400 transmitter allows a security lock-out of various menus. If the security lock-out feature of the transmitter has been enabled, a security password must be entered to allow access to the menu. See section 9.3 for more information.

### 3.2.8 Display



**NOTE:** In the event of an alarm or other error condition the M400 Transmitter will display a flashing  $\triangle$  a in the upper right corner of the display. This symbol will remain until the condition that caused it has been cleared.



**NOTE:** During calibrations (Channel A), clean, Digital In with Analog Output/OC, a flashing "H" (Hold) will appear in the upper left corner of the display. During calibration on Channel B, a flashing "H" (Hold) will appear in the second line. Change to B and flash. This symbol will remain for 20 sec., after end of calibration. This symbol will remain for 20 seconds until after the calibration or clean is completed. This symbol will also disappear when Digital In is deactivated.



**NOTE:** Channel A (A is shown on the left side of the display) indicates that a conventional sensor is connected to the transmitter.

Channel B (B is shown on the left side of the display) indicates, that an ISM Sensor is connected to the transmitter.

The M400 is a single input channel transmitter, and only one sensor can be connected at the same time.

## 4 Installation Instruction

### 4.1 Unpacking and Inspection of Equipment

Inspect the shipping container. If it is damaged, contact the shipper immediately for instructions. Do not discard the box.

If there is no apparent damage, unpack the container. Be sure all items shown on the packing list are present.


If items are missing, notify METTLER TOLEDO immediately.

#### 4.1.1 Panel Cutout Dimensional Information – ½ DIN Models

½ DIN Model transmitters are designed with an integral rear cover for stand-alone wall-mounted installation.

The unit may also be wall-mounted using the integral rear cover. See installation instructions in Section 4.1.2.

Below are the cut-out dimensions required by the ½ DIN models when mounted within a flat panel or on a flat enclosure door. This surface must be flat and smooth. Textured or rough surfaces are not recommended and may limit the effectiveness of the gasket seal provided.



Optional hardware accessories are available that allow for panel or pipe mounting. Refer to Section 15 for ordering information.

## 4.1.2 Installation Procedure

### General:

- Orient the transmitter so that the cable grips face downward.
- Wiring routed through the cable grips shall be suitable for use in wet locations.
- In order to provide IP66 enclosure ratings, all cable glands must be in place. Each cable gland must be filled using a cable, or suitable Cable Gland Hole Seal.


### For Wall-Mounting:

- Remove rear cover from front housing.
- Start by unscrewing the four screws located on the face of the transmitter, in each corner. This allows the front cover to swing away from the rear housing.
- Remove the hinge-pin by squeezing the pin from each end. This allows the front housing to be removed from the rear housing.
- Mount rear housing to wall. Secure mounting kit to the M400 according to the supplied instructions. Attach to wall using appropriate mounting hardware for the wall surface. Be sure it is level and securely fastened and the installation adheres to any and all clearance dimensions required for transmitter service and maintenance. Orient the transmitter so that the cable grips are facing downward.
- Replace the front housing to the rear housing. Securely tighten the rear-cover screws to ensure that IP66/NEMA4X enclosure environmental rating is maintained. The unit is ready to be wired.

### For Pipe-Mounting:


- Use only manufacturer-supplied components for pipe-mounting the M400 transmitter and install per the supplied instructions. See section 15 for ordering information.

## 4.1.3 Assembly – ½ DIN Version




1. 3 M20X1.5 cable glands
2. Plastics plugs
3. 4 screws

### 4.1.4 ½ DIN Version – Dimension Drawings



### 4.1.5 ½ DIN Version – Pipe-Mounting



## 4.2 Connection of Power Supply


All connections to the transmitter are made on the rear panel of all models.



Be sure the power to all wires is turned off before proceeding with the installation.

A two-terminal connector on the rear panel of all M400 models is provided for power connection. All M400 models are designed to operate from a 14–30 VDC power source. Refer to specifications for power requirements and ratings and size power wiring accordingly (AWG 16 – 24, wire cross-section 0.2 mm<sup>2</sup> to 1.5 mm<sup>2</sup>).


### 4.2.1 Housing (Wall-Mounting)



- 1: TB1 – Input and Output Signal
- 2: TB2 – Sensor Signal



### 4.3 Terminal Block (TB) Definitions



Power connections are labeled **A01+ /HART** and **A01- /HART** and **A02+** and **A02-** for 14 to 30 VDC.

### 4.4 Terminal Block TB1

Terminal	Designation	Description
1	DI1+	Digital input 1
2	DI1-	
3	DI2+	Digital input 2
4	DI2-	
5	Not used	-
6	OC1+	Open collector output 1 (switch)
7	OC1-	
8	OC2+	Open collector output 2 (switch)
9	OC2-	
10	A01+ /HART	- Power connection 14 to 30 V DC
11	A01- /HART	- Analog output signal 1 - HART signal
12	A02+	- Power connection 14 to 30 V DC
13	A02-	- Analog output signal 2
14	Not used	-
15	⏚	

## 4.5 Terminal Block TB2: Analog Sensors

### 4.5.1 Conductivity 4-e Analog Sensors

Terminal	Function	Color
A	Cnd inner1	White
B	Cnd outer1	White/blue
C	Cnd outer1	–
D	Not used	–
E	Cnd outer2	–
F	Cnd inner2	Blue
G	Cnd outer2 (GND)	Black
H	Not used	–
I	RTD ref/GND	Bare shield
J	RTD sense	Red
K	RTD	Green
L	Not used	–
M	Not used	–
N	Not used	–
O	Not used	–
P	Not used	–
Q	Not used	–

### 4.5.2 pH and Redox (ORP) Analog Sensors

Terminal	pH		Redox (ORP)	
	Function	Color <sup>1)</sup>	Function	Color
A	Glass	Transparent	Platinum	Transparent
B	Not used	–	–	–
C	Not used	–	–	–
D	Not used	–	–	–
E	Reference	Red	Reference	Red
F	Reference <sup>2)</sup>	–	Reference <sup>2)</sup>	–
G	Solution GND <sup>2)</sup>	Blue <sup>3)</sup>	Solution GND <sup>2)</sup>	–
H	Not used	–	–	–
I	RTD ref/GND	White	–	–
J	RTD sense	–	–	–
K	RTD	Green	–	–
L	Not used	–	–	–
M	Shield (GND)	Green/yellow	Shield (GND)	Green/yellow
N	Not used	–	–	–
O	Not used	–	–	–
P	Not used	–	–	–
Q	Not used	–	–	–

1) Gray wire not used.

2) Install jumper between F and G for ORP sensors and pH electrodes without SG.

3) Blue wire for electrode with SG.


## 4.6 Terminal Block TB2: ISM Sensors

### 4.6.1 pH ISM Sensors

Terminal	Function	Color
A	Not used	–
B	Not used	–
C	Not used	–
D	Not used	–
E	Not used	–
F	Not used	–
G	Not used	–
H	Not used	–
I	Not used	–
J	Not used	–
K	Not used	–
L	1-wire	Transparent (cable core)
M	GND	Red (shield)
N	RS485-B	–
O	RS485-A	–
P	+Ain	–
Q	–Ain	–

## 4.7 Connection of ISM Sensors

### 4.7.1 Connection of ISM Sensors for pH/ORP




**NOTE:** Connect the sensor and screw the plug head clockwise (hand tight).

### 4.7.2 TB2 – AK9 Cable Assignment

- \* 1-wire data (transparent)
- \*\* Ground/shield

## 4.8 Connection of Analog Sensors

### 4.8.1 Connection of Analog Sensor for pH/ORP




**NOTE:** Cable lengths > 20 m can worsen the response during pH measurement. Be sure to observe the sensor instruction manual.

## 4.8.2 TB2 – Typical Wiring for Analog pH/ORP Sensor

### 4.8.2.1 Example 1

pH measurement without Solution Ground




**NOTE:** Jumper terminals G and F

Wire colors only valid for connection with VP cable; blue and gray not connected.

A: Glass  
 E: Reference  
 I: RTD ret/GND  
 K: RTD  
 M: Shield/GND

### 4.8.2.2 Example 2

pH measurement with Solution Ground




**NOTE:** Wire colors only valid for connection with VP cable, gray not connected.

A: Glass  
 E: Reference  
 G: Shield/Solution GND  
 I: RTD ret/GND  
 K: RTD  
 M: Shield(GND)

### 4.8.2.3 Example 3

ORP (redox) measurement (temperature optional)




**NOTE:** Jumper terminal G and F

A: Platinum  
 E: Reference  
 I: RTD ref/GND  
 K: RTD  
 M: Shield(GND)



### 4.8.2.4 Example 4

ORP measurement with pH solution ground electrode (e.g. InPro 3250 SG, InPro 4800 SG).



**NOTE:** Jumper terminal G and F

A: Platinum  
 E: Reference  
 I: RTD ret/GND  
 K: RTD  
 M: Shield(GND)

## 5 Placing Transmitter in or out of Service

### 5.1 Placing Transmitter in Service



After connecting the transmitter to the power supply circuit, it will be active as soon as the circuit is powered.

### 5.2 Placing Transmitter out of Service

First disconnect the unit from the main power source, then disconnect all remaining electrical connections. Remove the unit from the wall/panel. Use the installation instruction in this manual as reference for disassembling mounting hardware.

All transmitter settings stored in memory are non-volatile.

## 6 Quick Setup

(PATH: Menu/Quick Setup)

Select Quick Setup and press the [ENTER] key. Enter the security code if necessary (see section 9.2 "Passwords")



**NOTE:** Please find the complete description of the Quick Setup routine described in the separate booklet "Quick Setup Guide for Transmitter M400" enclosed in the box.



**NOTE:** Please do not use Quick Setup menu after configuration of the transmitter, because some of the parameters i.e. analog output configuration may have been reset.



**NOTE:** Refer to section 3.2 "Control/Navigation Keys" for information on menu navigation.

## 7 Sensor Calibration

(PATH: Cal)

The calibration key ► allows the user one-touch access to sensor calibration and verification features.



**NOTE:** During Calibration on Channel A, a flashing "H" (Hold) in the upper left corner of the Display indicates a calibration is in process with a Hold condition active. (The hold output needs to be activated.) See also chapter 3.2.8 "Display".

### 7.1 Enter Calibration Mode

While in Measurement mode press the ► key. If the display prompts you to enter the Calibration security code, press the ▲ or ▼ key to set the calibration security mode, the [ENTER] key to confirm the calibration security code.

Press the ▲ or ▼ key to select the type of calibration desired.

#### 7.1.1 Select the Desired Sensor Calibration Task

For analog sensors depending on sensor type, the following choices are available:

Analog sensor	Calibration task
Conductivity	Conductivity, Resistivity, Temperature, Edit, Verify
pH	pH, mV, Temperature, Edit pH, Edit mV, Verify

For ISM (digital) sensors depending on sensor type, the following choices are available:

ISM sensor	Calibration task
pH	pH, ORP, Verify

## 7.1.2 Finish Calibration

After every successful calibration the following options are available.

### **Analog sensors**

Adjust: Calibration values are stored in the transmitter and used for the measurement. Additionally, the calibration values are stored in the calibration data.

Calibrate: The function "Calibrate" is not applicable for analog sensors.

Abort: Calibration values are discarded.

### **ISM (digital) sensors**

Adjust: Calibration values are stored in the sensor and used for the measurement. Additionally, the calibration values are stored in the calibration history.

Calibrate: Calibration values are stored in the calibration history for documentation, but not be used for the measurement. The calibration values from the last valid adjustment are further used for the measurement.

Abort: Calibration values are discarded.

After selection the message "RE-INSTALL SENSOR and Press [ENTER]" appears on the display. Press [ENTER] to return to the measuring mode.

## 7.2 Conductivity Calibration for Four-Electrode Sensors

This feature provides the ability to perform a one-point, two-point or process Conductivity, and Resistivity Sensor calibration for four-electrode sensors.



**NOTE:** When performing calibration on a conductivity sensor, results will vary depending on the methods, calibration apparatus and/or quality of reference standards used to perform the calibration.



**NOTE:** For measuring tasks the temperature compensation for the application as defined at the menu Resistivity will be considered and not the temperature compensation selected thru the calibration procedure (see also chapter 8.2.3.1 "Conductivity Temperature Compensation"; PATH: Menu/Configure/Measurement/Resistivity).

Enter Conductivity sensor calibration mode as described in section 7.1 "Enter Calibration Mode".

The next screen will ask to select the type of temperature compensation mode desired during the calibration process.

Choices are "Standard", "Lin 25 °C", "Lin 20 °C" or "Nat H2O" compensation mode.

Standard compensation: includes compensation for non-linear high purity effects as well as conventional neutral salt impurities and conforms to ASTM standards D1125 and D5391.

Lin 25°C compensation: adjusts the reading by a factor expressed as "% per °C" deviation from 25 °C. The factor can be modified.

Lin 20°C compensation: adjusts the reading by a factor expressed as "% per °C" deviation from 20 °C. The factor can be modified.

Nat H2O compensation: includes compensation to 25 °C according to EN27888 for natural water.

Choose the compensation mode, modify the factor where appropriate and press [ENTER].

### 7.2.1 One-Point Sensor Calibration

(Display reflects typical Conductivity Sensor calibration)

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.2 "Conductivity Calibration for Four-Electrode Sensors").

Select 1 point calibration and press [ENTER]. With conductivity sensors a one-point calibration is always performed as a slope calibration.

Place the electrode into the reference solution.

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable to perform the calibration.

After the calibration, the cell multiplier or slope calibration factor "M", i.e. cell constant, and the Adder or offset calibration factor "A" are displayed.

For ISM (digital) sensors, select ADJUST, CALIBRATE or ABORT to finish calibration. For Analog sensors select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".

## 7.2.2 Two-Point Sensor Calibration

(Display reflects typical Conductivity sensor calibration)

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.2 "Conductivity Calibration for Four-Electrode Sensors").

Select 2 point calibration and press [ENTER].

Place the electrode into the first reference solution.



**CAUTION:** Rinse sensors with a high-purity water solution between calibration points to prevent contamination of the reference solutions.

Enter the value for Point 1 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable and place the electrode into the second reference solution.

Enter the value for Point 2 including a decimal point and units. The value in the second text line is the value being measured by the transmitter and sensor in the units selected by the user. Press [ENTER] when this value is stable to perform the calibration.

After the calibration of the cell multiplier or slope calibration factor "M", i.e. cell constant, and the Adder or offset calibration factor "A" are displayed.

For ISM (digital) sensors, select ADJUST, CALIBRATE or ABORT to finish calibration. For Analog sensors select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".

### 7.2.3 Process Calibration

(Display reflects typical Conductivity sensor calibration)

Enter Conductivity Sensor Calibration mode as described in section 7.1 "Enter Calibration Mode" and choose one of the compensation modes (see section 7.2 "Conductivity Calibration for Four-Electrode Sensors").

Select Process Calibration and press [ENTER]. With conductivity sensors a process calibration is always performed as a slope calibration.

Take a sample and press the [ENTER] key again to store the current measuring value.

During the ongoing calibration process, the letter of the channel, which is concerned by the calibration, "A" or "B" will blink in the display.

After determining the conductivity value of the sample, press the [CAL] key again to proceed with the calibration.

Enter the conductivity value of the sample, then press the [ENTER] key to start the calculation of calibration results.

After the calibration the Multiplier or slope calibration factor "M" and the Adder or offset calibration factor "A" are displayed.

For ISM (digital) sensors select ADJUST, CALIBRATE or ABORT to finish calibration. For Analog sensors select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".



## 7.3 pH Calibration


For pH sensors, the M400/2XH Type 1 transmitter features one-point, two-point (Auto or Manual mode) or process calibration with 9 preset buffer sets or manual buffer entry. Buffer values refer to 25 °C. To calibrate the instrument with automatic buffer recognition, you need a standard pH buffer solution that matches one of these values. (See section 8.2.3.3 "pH/ORP Parameters" for configuring modes and selecting buffer sets.) Please select the correct buffer table before using automatic calibration (see chapter 19 "Buffer Tables").




**NOTE:** For dual membrane pH electrodes (pH/pNa) only buffer Na<sup>+</sup> 3.9M (see section 19.2.1 "Mettler-pH/pNa Buffers") is available.

### 7.3.1 One-Point Calibration

Enter pH calibration mode as described in section 7.1 "Enter Calibration Mode".




Select one-point Calibration. With pH sensors a one point calibration is always performed as a offset calibration.




Depending on the parameterized Drift control (see chapter 8.2.3.3 "pH parameters"), one of the two following modes is active.

#### 7.3.1.1 Auto Mode


Place the electrode in the buffer solution and press the [ENTER] key to start the calibration.



The display shows the buffer the transmitter has recognized (Point 1) and the measured value.




As soon as the stabilization criteria have been fulfilled, the display changes. The display shows now the slope calibration factor "S" and the offset calibration factor "Z".




For ISM (digital) sensors, select ADJUST, CALIBRATE or ABORT to finish calibration. For Analog sensors, select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".

### 7.3.1.2 Manual Mode



Place the electrode in the buffer solution. The display shows the buffer the transmitter has recognized (Point 1) and the measured value. Press [ENTER] to proceed.




The display shows now the slope calibration factor "S" and the offset calibration factor "Z".

For ISM (digital) sensors, select ADJUST, CALIBRATE or ABORT to finish calibration. For Analog sensors select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".

## 7.3.2 Two-Point Calibration




Enter pH calibration mode as described in section 7.1 "Enter Calibration Mode".




Select 2 Point calibration.

Depending on the parameterized Drift control (see chapter 8.2.3.3 "pH Parameters"), one of the two following modes is active.


### 7.3.2.1 Auto Mode



Place the electrode in the first buffer solution and then press the [ENTER] key.




The display shows the buffer the transmitter has recognized (Point 1) and the measured value.




As soon as the stabilization criteria have been fulfilled, the display changes and prompts you to place the electrode in the second buffer.

Place the electrode in the second buffer solution and press the [ENTER] key to go on with the calibration.




The display shows the second buffer the transmitter has recognized (Point 2) and the measured value.




As soon as the stabilization criteria have been fulfilled, the display changes to show the slope calibration factor "S" and the offset calibration factor "Z".

For ISM (digital) sensors, select ADJUST, CALIBRATE or ABORT to finish calibration. For analog sensors select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".


### 7.3.2.2 Manual Mode



Place the electrode in the first buffer solution. The display shows the buffer the transmitter has recognized (Point 1) and the measured value. Press [ENTER] to proceed.




Place the transmitter in the second buffer solution. The display shows the buffer the transmitter has recognized (Point 2) and the measured value. Press [ENTER] to proceed.




The display shows the slope calibration factor "S" and the offset calibration factor "Z".

For ISM (digital) sensors, select ADJUST, CALIBRATE or ABORT to finish calibration. For analog sensors select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".


### 7.3.3 Process Calibration



Enter pH calibration mode as described in section 7.1 "Enter Calibration Mode".




Select Process calibration. With pH sensors a process calibration is always performed as an offset calibration.




Take a sample and press the [ENTER] key again to store the current measuring Value. To show the ongoing calibration process, "A" or "B" (depending on the channel) will blink in the display.



After determining the pH value of the sample, press the [CAL] key again to proceed with the calibration.




Enter the pH value of the sample then press the [ENTER] key to start the calculation of the calibration results.




After the calibration the slope calibration factor "S" and the offset calibration factor "Z" are displayed.

For ISM (digital) sensors, select ADJUST, CALIBRATE or ABORT to finish calibration. For Analog sensors select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".


### 7.3.4 mV Calibration (only for analog sensors)



Enter mV calibration mode as described in section 7.1 "Enter Calibration Mode".



The user can now enter Point 1. The offset calibration factor is calculated by using the value of Point1 instead of the measured value (line 4, mV = ....) and displayed on the next screen.



"Z" is the newly calculated offset calibration factor. The slope calibration factor "S" is always 1 and does not enter the calculation.


Select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".

### 7.3.5 ORP Calibration (only for ISM sensors)


In the case that an pH sensor with solution ground based on ISM technology is connected to the M400, the transmitter gives the option to make in addition to the pH calibration an ORP calibration.



**NOTE:** If an ORP calibration is selected, the parameters defined for pH (see chapter 8.2.3.3 "pH/ORP Parameters", PATH: Menu/Configure/Measurement/pH) will not be considered.




Enter ORP calibration mode as described in section 7.1 "Enter Calibration Mode".



The user can now enter Point 1. In addition the actual ORP is displayed.


Press [ENTER] to proceed.



The display shows the slope calibration factor "S" and the offset calibration factor "Z".


Select ADJUST, CALIBRATE or ABORT to finish calibration. See "7.1.2 Finish Calibration".

## 7.4 Sensor Temperature Calibration (only for analog sensors)




Enter Sensor calibration mode as described in section 7.1 "Enter Calibration Mode" and select Temperature.

### 7.4.1 One-Point Sensor Temperature Calibration



Select one-point calibration. Slope or Offset can be selected with the one-point calibration. Select Slope to recalculate the Slope factor "M" (Multiplier) or Offset to recalculate the offset calibration factor "A" (Adder).




Enter the value for Point 1 and press [ENTER].




Select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".

### 7.4.2 Two-Point Sensor Temperature Calibration



Select Two-Point as calibration type.



Enter the value for Point 1 and press [ENTER].

```

A  1.25  μS/cm
A  25.00  °C
A Point2 = 50.00 °C
A    T = 50.64 °C ▲

```

Enter the value for Point 2 and press [ENTER].

```

1.25  μS/cm
A  25.00  °C

Temp M=0.99994 A=0.00000
Save Adjust ↑

```

Select ADJUST or ABORT to finish calibration. See "7.1.2 Finish Calibration".

## 7.5 Edit Sensor Calibration Constants (only for analog sensor)

```

A  1.25  μS/cm
A  25.00  °C
Calibrate Sensor
Channel A Edit ▲

```

Enter Calibration mode as described in section 7.1 "Enter Calibration Mode" and select Edit, Edit pH, Edit mV.

```

A  1.25  μS/cm
A  25.00  °C
Ap M=0.1000 A=0.0000
As M=0.1000 A=0.0000 ▲

```

All calibration constants for the selected sensor channel are displayed. Primary measurement constants (p) are displayed on Line 3. Secondary measurement (temperature) constants (s) for the sensor are displayed on Line 4.

The calibration constants can be changed in this menu.

```

A  1.25  μS/cm
A  25.00  °C
Save Calibration Yes
Press ENTER to Exit ▲

```

Select Yes to save the new calibration values and the successful calibration is confirmed on the display.



**NOTE:** Each time a new analog conductivity sensor is connected to the M400/2XH Type 1 transmitter, it is necessary to enter the unique calibration data (cell constant and offset) located on the sensor label.

## 7.6 Sensor Verification

```

A  1.25  μS/cm
A  25.00  °C
Calibrate Sensor
Channel A Verify ▲

```

Enter Calibration mode as described in section 7.1. "Enter Calibration Mode" and select Verify.

```

A  1.25  μS/cm
A  25.00  °C
Verify Cal:Channel A
Ch A 1.820 MΩ 1.097 KΩ


```

The measured signal of the primary and the secondary measurement in electrical units are shown. The meter calibration factors are used when calculating these values.

Press [ENTER] to exit from this display.

## 8 Configuration

(PATH: Menu/Configure)



\* Only available in combination with ISM sensors


### 8.1 Enter Configuration Mode



While in Measurement mode, press the ◀ key. Press the ▲ or ▼ key to navigate to the Configure menu and press [ENTER].

### 8.2 Measurement

(PATH: Menu/Configure/Measurement)




Enter configuration mode as described in Section 8.1 "Enter Configuration Mode".

Press the [ENTER] key to select this menu. The following sub menus can now be selected: Channel Setup, Temperature Source, pH and Set Averaging.

#### 8.2.1 Channel Setup


(PATH: Menu/Configure/Measurement/Channel Setup)



Press the [ENTER] key to select the "Channel Setup" menu.

Depending on the connected sensor (analog or ISM) the channel can be chosen.

### 8.2.1.1 Analog Sensor



Select sensor type Analog and press [ENTER].


Available measurement types are (depends on transmitter type):

Measurement parameter	Description	Transmitter M400/2XH Type 1
pH/ORP	InPro 2xxx	•
	InPro 31xx	–
	InPro 32xx	•*
	InPro xxx3	–
	InPro 33xx	–
	InPro 4xxx	•
Cond (2)	2 electrode conductivity	–
Cond (4)	4 electrode conductivity	•

\* Exclude InPro 3253i

The 4 lines of the display can now be configured with sensor channel "A" for each line of the display as well as measurements and unit multipliers. Pressing the [ENTER] key will display the selection for lines a, b, c and d.

### 8.2.1.2 ISM Sensor



Select sensor type ISM and press [ENTER].

If an ISM sensor is connected, the transmitter automatically (Parameter = Auto) recognizes the type of sensor. You can also fix the transmitter to a certain measurement parameter, e.g. "pH", depending on the type of transmitter you have.

Measurement parameter	Description	Transmitter M400/2XH Type 1
pH/ORP	InPro 2xxxi	•
	InPro 31xxi	–
	InPro 32xxi	•*
	InPro xxx3i	–
	InPro 42xxi	•
	InPro X1 XLS/XPS	•
pH/pNa	InPro 48xxi	•
Cond (4)	InPro 7100i	–

\* Exclude InPro 3253i


The 4 lines of the display can now be configured with sensor channel "A" for each line of the display as well as measurements and unit multipliers. Pressing the [ENTER] key will display the selection for lines a, b, c and d.



**NOTE:** In addition to the measurement values, the ISM values DLI, TTM and ACT can also be assigned to the different lines and linked to the analog outputs (see Chapter 8.3 "Analog Outputs") or set points (see chapter 8.4 "Set Points")




### 8.2.1.3 Save Changes of the Channel Setup



After the procedure of the channel setup described in the previous chapter pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.

## 8.2.2 Temperature Source (only for analog sensors)

(PATH: Menu/Configure/Measurement/Temperature Source)



Enter Measurement as described in chapter 8.2 "Measurement". Select Temperature Source by using the ▲ or ▼ key and press [ENTER].




The following options can be chosen:

- Auto: The transmitter automatically recognizes the temperature source.
- Use NTC22K: Input will be taken from the sensor attached.
- Use Pt1000: Temperature input will be taken from the sensor attached
- Use Pt100: Input will be taken from the sensor attached.
- Fixed = 25 °C: Allows a specific temperature value to be entered. It must be chosen when the customer uses the pH sensor without temperature source.



**NOTE:** If the temperature source is set to Fixed, the temperature applied during one-point and/or two-point calibration of pH electrodes can be adjusted within the corresponding calibration procedure. After the calibration the fixed temperature defined in this configuration menu is valid again.

Pressing the [ENTER] key will bring up the Save Changes dialog.



Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.

## 8.2.3 Parameter-related Settings


(PATH: Menu/Configure/Measurement/pH)

Additional measurement and calibration parameters can be set for each parameter, conductivity and pH.



**NOTE:** Use pH menu for settings of pH/pNa sensors.

Enter Configuration Mode as described in section 8.1 "Enter Configuration Mode" and select the menu Measurement (see section 8.2 "Configuration/Measurement").



Depending on the connected sensor, the menu can be selected by using the A or ▼ key. Press [ENTER]

For more details, please see the following explanations depending on the selected parameter.

### 8.2.3.1 Conductivity Temperature Compensation

If, during the channel setup (see chapter 8.2.1 "Channel Setup"), the parameter conductivity has been chosen the temperature compensation mode can be selected. Temperature compensation should be matched to the characteristics of the application. The transmitter considers this value for the temperature compensation by calculating and displaying the result for the measured conductivity.




**NOTE:** For calibration purposes the temperature compensation as defined at the menu "Cal/Compensation" for the buffers or samples will be considered (see also chapter 7.2 "Conductivity Calibration for Four-Electrode Sensors").


For this adjustment, the menu "Resistivity", that will be displayed, has to be chosen. (See chapter 8.2.3 "Parameter-related Settings").

The first two measurement lines are displayed on the screen. This chapter described the procedure for the first measurement line. The key ► selects the second line. To select the 3rd and 4th line press [ENTER]. The procedure itself works at every measurement line in the same way.

Choices are "Standard", "Lin 25°C" and "Lin 20°C".




Standard compensation includes compensation for non-linear high purity effects as well as conventional neutral salt impurities and conforms to ASTM standards D1125 and D5391.




Lin 25 °C compensation adjusts the reading by a factor expressed as a "% per °C" (deviation from 25 °C). Use only if the solution has a well-characterized linear temperature coefficient.

The factory default setting is 2.0%/°C.



Lin 20 °C compensation adjusts the reading by a factor expressed as a "% per °C" (deviation from 20 °C). Use only if the solution has a well-characterized linear temperature coefficient.

The factory default setting is 2.0%/°C



If compensation mode "Lin 25 °C" or "Lin 20 °C" has been chosen, the factor for the adjustment of the reading can be modified after pressing [ENTER] (If working at measurement line 1 or 2 press [ENTER] twice).

Adjust the factor for temperature compensation.

Pressing [ENTER] will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.

### 8.2.3.2 Concentration Table

If during the channel setup (see chapter 8.2.1 "Channel Setup") the parameter conductivity has been chosen a concentration table can be defined.

To specify customer-specific solutions, up to 9 concentration values can be edited in a matrix together with up to 9 temperatures. To do so the desired values are edited under the concentration table menu. Furthermore the conductivity values for the according temperature and concentration values are edited.

If in the settings the menu "Concentration Table" has to be chosen and will be displayed, see chapter 8.2.3 "Parameter-related Settings".




Define the desired **unit**.

Press [ENTER]




**NOTE:** Refer to section 8.2.1 "Channel Setup" to choose the unit used in the display.




Enter the amount of desired temperature points "Temp Point" and "Concentration Points".

Press [ENTER]



Enter the values for the different concentrations (**ConcentrationX**).

Press [ENTER]



Enter the value of the 1st temperature (**Temp1**) and the value for the conductivity which belongs to the first concentration at this temperature.

Press [ENTER]

Enter the value for the conductivity which belongs to the second concentration at the first temperature and press [ENTER] etc..

After entering all conductivity values that belong to the different concentrations at the first temperature point, enter in the same way the value of the 2nd temperature point (**Temp2**) and the conductivity value which belongs at the second temperature to the first concentration. Press [ENTER] and go on in the same way for the next concentration points as described for the first temperature point.

Enter in this way the values at every temperature point. After entering the last value, pressing [ENTER] again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.



**NOTE:** The values for the temperature have to increase from Temp1 to Temp2 to Temp3 etc.. The values for the concentration have to increase from Concentration1 to Concentration2 to Concentration3 etc..




**NOTE:** The conductivity values at the different temperatures have to increase or decrease from Concentration1 to Concentration2 to Concentration3 etc.. Maxima and/or minima are not permitted. If the conductivity values at Temp1 are increasing with the different concentrations, they have to increase also at the other temperatures. If the conductivity values at Temp1 are decreasing with the different concentrations, they have to decrease also at the other temperatures.

### 8.2.3.3 pH/ORP Parameters

If, during the channel setup (see chapter 8.2.1 "Channel Setup"), the parameter pH/ORP has been chosen or an pH sensor based on ISM technology is connected to the transmitter, the parameters drift control, buffer recognition, STC, I P, fixed Calibration temperature and the displayed units for slope and zero point can be set or adjusted.

For making these adjustments or entering these settings, the menu "pH" has to be chosen and will be displayed. (See chapter 8.2.3 "Parameter-related Settings").




Select the **drift control** for calibration as Auto (drift and time criteria have to be fulfilled) or manual (the user can decide when a signal is stable enough to complete calibration) followed by the relevant buffer table for the automatic buffer recognition. If the drift rate is less than 0.4 mV over a 19 second interval then the reading is stable and the calibration is done using the last reading. If the drift criteria is not met within 300 seconds then the calibration times out and the message "Calibration Not Done" Press ENTER Enter to "Exit" is displayed.

Press [ENTER]


For automatic **buffer recognition** during calibration, select the buffer solution set that will be used: Mettler-9, Mettler-10, NIST Tech, NIST Std = JIS Std, HACH, CIBA, MERCK, WTW, JIS Z 8802 or None. See Section 19 "Buffer Tables" for buffer values. If the auto buffer feature will not be used or if the available buffers are different from those above, select None. Press [ENTER].



**NOTE:** For dual membrane pH electrodes (pH/pNa) only buffer Na<sup>+</sup> 3.9M (see section 19.2.1 "Mettler-pH/pNa Buffers") is available.




**STC** is the solution temperature coefficient in units of pH/°C referenced to 25 °C (Default = 0.000 for most applications). For pure waters, a setting of 0.016 pH/°C should be used. For low conductivity power plant samples near 9 pH, a setting of 0.033 pH/°C should be used. These positive coefficients compensate for the negative temperature influence on the pH of these samples. Press [ENTER].



**IP** is the isothermal point value (Default = 7.000 for most applications). For specific compensation requirements or non standard inner buffer value, this value can be changed. Press [ENTER].



**STC RefTemp** sets the temperature to which solution temperature compensation is referenced. The displayed value and the output signal is referenced to STC RefTemp. Selecting "No" means solution temperature compensation is not used. The most common reference temperature is 25°C. Press [ENTER].




The units for the slope and the zero point that will be shown on the display can be chosen. The default setting for the unit of the slope is [%] and can be changed to [pH/mV]. For the zero point the default setting of the unit is [pH] and can be changed to [mV]. Use the ► key to move to the input field and select the unit by using the ▲ or ▼ key.

Pressing [ENTER] again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.


## 8.2.4 Set Averaging

Enter Configuration Mode as described in section 8.1 "Enter Configuration Mode" and select the menu Measurement (see section 8.2 "Configuration/Measurement").

Selected the menu "Set Averaging" by using the ▲ or ▼ key. Press [ENTER]




The averaging method (noise filter) for each measurement line can now be selected. The options are Special (Default), None, Low, Medium and High:



None = no averaging or filtering  
 Low = equivalent to a 3-point moving average  
 Medium = equivalent to a 6-point moving average  
 High = equivalent to a 10-point moving average  
 Special = averaging depending on signal change (normally High averaging but Low averaging for large changes in input signal)

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.




## 8.3 Analog Outputs

(PATH: Menu/Configure/Analog Outputs)

Enter Configuration mode as described in Section 8.1. "Enter Configuration Mode" and navigate to the menu "Analog Outputs" by using the ▲ or ▼ key.

Press the [ENTER] key to select this menu, which lets you configure the 4 analog outputs.

Once analog outputs have been selected, use the ◀ and ▶ buttons to navigate between configurable parameters. Once a parameter is selected, its setting can be selected per the following table:



When an alarm value is selected (see chapter 8.5.1 "Alarm"; PATH: Menu/Configure/Alarm/Clean/Setup Alarm), the analog output will go to this value if any of these alarm conditions occurs.

With the "Aout1 Measurement = a" parameter the analog output 1 is assigned to the measured value "a". With the "Aout2 Measurement = b" parameter the analog output 2 is assigned to the measured value "b".



**NOTE:** In addition to the measurement values, the ISM values DLI, TTM and ACT can also be linked to the analog outputs if they have been assigned to the corresponding line in the display (see chapter 8.2.1.2 "ISM Sensor")

With the "If Alarm Set" parameter the current is set to 3.6 mA or 22.0 mA (default) in case of an alarm.

The "AoutX Type" parameter is "Normal". The "AoutX Range" parameter is "4–20 mA".

Enter the minimum and maximum value of Aout.

```
A 0.28  μS/cm
A 24.97 °C
Aout1 Type= Normal
Aout1 Range = 4-20 ▲
```

```
0.28  μS/cm
24.97 °C
Aout1 min= 0.000 μS/cm
Aout1 max= 10.00 μS/cm ▲
```

```
A 0.28  μS/cm
A 24.97 °C
Aout1 max1=20.00 MΩ-cm ▲
```

```
A 0.28  μS/cm
A 24.97 °C
Aout1 hold mode
Last Value ▲
```

```
A 0.28  μS/cm
A 24.97 °C
Save Change Yes & Exit
Press ENTER to Exit ▲
```

If Auto-Range was selected then Aout max1 can be configured. Aout max1 is the maximum value for the first range on auto-range. The maximum value for the second range on auto-range was set in the previous menu. If Logarithmic Range was selected, it will also prompt for the number of decades as "Aout1 # of Decades =2".

The value for the Hold mode can be configured to hold the last value or can be set to a fixed value.

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.

## 8.4 Set Points

(PATH: Menu/Configure/Set Points)

Enter Configuration mode as described in Section 8.1. "Enter Configuration Mode" and navigate to the menu "Set Points" by using the ▲ or ▼ key.

Press the [ENTER] key to select this menu.

```
A 0.28  μS/cm
A 25.00 °C
Configure
Set Points ▲
```

Up to 6 setpoints can be configured on any of the measurements (a thru d). The possible Setpoint types are Off, High, Low, Outside (<->) and Between (>-<).

An "Outside" setpoint will cause an alarm condition whenever the measurement goes above its high limit or below its low limit. A "Between" setpoint will cause an alarm condition to occur whenever the measurement is between its high and low limits.

Enter the desired value(s) for the setpoint and press [ENTER]




**NOTE:** In addition to the measurement values, the ISM values DLI, TTM and ACT can also be linked to the set points if they have been assigned to the corresponding line in the display (see chapter 8.2.1.2 "ISM Sensor").



Depending on the defined setpoint type, this screen provides the option to adjust the values for the setpoint(s).


Press [ENTER] to proceed.



#### Out of Range

Once configured, the selected OC will be activated if a sensor Out of Range condition is detected on the assigned input channel. Select the setpoint and "Yes" or "No". Select the desired OC that will activate when the setpoint alarm condition is reached.

Press [ENTER]



#### Delay


Enter the delay time in seconds. A time delay requires the setpoint to be exceeded continuously for the specified length of time before activating the OC. If the condition disappears before the delay period is over, the OC will not be activated.

#### Hysteresis

Enter value for the hysteresis. A hysteresis value requires the measurement to return within the setpoint value by a specified hysteresis before the OC is deactivated.

For a high setpoint, the measurement must decrease more than the indicated hysteresis below the setpoint value before the OC is deactivated. With a low setpoint, the measurement must rise at least this hysteresis above the setpoint value before the OC is deactivated. For example, with a high setpoint of 100 and hysteresis of 10, when this value is exceeded, the measurement must fall below 90 before the OC is deactivated.

Press [ENTER]



#### Hold

Enter the OC Hold Status of "Last", "On" or "Off". This is the state the OC will go to during a hold status.

#### State

OC contacts are in normal state until the associated setpoint is exceeded, then the OC is activated and the contact states change.

Select "Inverted" to reverse the normal operating state of the OC (i.e. normally high voltage state is in a low voltage state until the setpoint is exceeded). "Inverted" OC operation is functional vice versa. All OCs can be configured.


Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.

## 8.5 Alarm/Clean

(PATH: Menu/Configure/Alarm/Clean)

Enter configuration mode as described in Section 8.1 "Enter Configuration Mode".

This menu allows the configuration of alarm and clean functionality.



### 8.5.1 Alarm


To select "Setup Alarm", press the ▲ or ▼ key so that "Alarm" is flashing.

Using the ◀ and ▶ buttons, navigate to "Use OC #". Using the ▲ or ▼ keys, select a OC to be used for the alarm and press [ENTER].

One of the following events may be alarmed:

1. Power failure
2. Software failure
3. Rg diagnostics – pH glass membrane resistance (only for pH,; pH/pNa Rg diagnostics detect both pH and pNa membrane glasses)
4. Rr diagnostics – pH reference resistance (only for pH sensors; except pH/pNa)
5. Cond cell open (only for analogue 4-e sensors)
6. Cond cell shorted (only for analogue 4-e sensors)
7. Channel B disconnected (only for ISM sensors)

If any of these criteria are set to Yes and the conditions for an alarm are given, the flashing symbol  $\triangle$  will be shown in the display, an alarm message will be recorded (see also chapter Messages; PATH: Info/Messages) and the selected OC will be activated. Furthermore an alarm can be indicated by the current output if this has been parameterized (see chapter 8.3 "Analog Outputs"; PATH: Menu/Configure/Analog Outputs)



The conditions for alarms are:

1. There is a power failure or power cycling
2. The software watchdog performs a reset
3. Rg is out of tolerance – for example, broken measuring electrode (only for pH; pH/pNa Rg diagnostics detect both pH and pNa membrane glasses)
4. Rr is out of tolerance – for example, coated or depleted reference electrode (only for pH sensors; except pH/pNa)
5. If the conductivity sensor is on air (for example in an empty pipe) (only for resistive Conductivity sensors)
6. If the conductivity sensor has a short cut (only for resistive conductivity sensors)
7. If no sensor is connected on channel B (only for ISM sensors)
8. If the conductivity sensor is on air (for example in an empty pipe) (only for ISM Conductivity sensors)
9. Electrolyte in the membrane body reaches such a low level that the connection between cathode and reference is disturbed, an immediate action must be taken e.g. exchange and filling the electrolyte.

For 1 and 2 the alarm indicator will be turned off when the alarm message is cleared. It will reappear if the power is constantly cycling or if the watchdog is repeatedly resetting the system.

#### Only for pH sensors

For 3 and 4 the alarm indicator will go off if the message is cleared and the sensor has been replaced or repaired so that the Rg and Rr values are within specification. If the Rg or Rr message is cleared and Rg or Rr is still out of tolerance then the alarm will stay on and the message will



reappear. The Rg and Rr alarm can be turned off by going into this menu and setting Rg diagnostics and/or Rr diagnostics to No. The message can then be cleared and the alarm indicator will be off even though Rg or Rr is out of tolerance.

```

A  0.28  μS/cm
A  25.00  °C
Relay State = Inverted
R2 Delay = 001 sec ▲

```



Each alarm OC can be configured in either a Normal or Inverted state. In addition, a Delay for the activation can be set. For more information, refer to Section 8.4 "Setpoints".

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values, while selecting Yes will make the entered values the current ones.

**NOTE:** There are additional alarms, which will be indicated in the display. See therefore in chapter 14 "Troubleshooting" the different warning and alarm lists.

## 8.5.2 Clean

Configure the OC to be used for the cleaning cycle.

The default value is OC 1.

```

A  0.28  μS/cm
A  25.00  °C
Setup Clean
Use Relay # 1 ▲

```

The cleaning interval can be set from 0.000 to 999.9 hours. Setting it to 0 turns the clean cycle off. The cleaning time can be 0 to 9999 seconds and must be smaller than the cleaning interval.

Select the desired OC state: Normal or Inverted.

```

A  0.28  μS/cm
A  25.00  °C
CleanInterval= 0.000 hrs
Clean Time = 0000 sec ▲

```

Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.

```

A  0.28  μS/cm
A  25.00  °C
Relay State = Normal ▲


```

## 8.6 ISM Set Up (available for pH ISM sensors)

(PATH: Menu/Configure/ISM Setup)


Enter Configuration mode as described in Section 8.1. "Enter Configuration Mode" and navigate to the menu "ISM set up" by using the ▲ or ▼ key. Press [ENTER]

### 8.6.1 Sensor Monitoring



Select the menu "Sensor Monitoring" by pressing [ENTER].

The sensor monitoring options can be turned on or off and every alarm can be assigned to a certain output OC. The following options are possible:



**Lifetime indicator:** The dynamic lifetime indication allows an estimation, when the pH electrode is at the end of his lifetime, based on the actual stress he is exposed to. The sensor permanently takes the averaged stress of the past days into consideration and is able to increase/decrease the lifetime accordingly.

Lifetime Indicator	YES/NO		
Alarm	YES/NO	R#	choose OC

The following parameters affect the lifetime indicator:


Dynamic parameters:	Static parameters:
– Temperature	– Calibration history
– pH value	– Zero and Slope
– Glass impedance	
– Reference impedance	

The sensor keeps the information stored in the built in electronics and can be retrieved via a transmitter or the iSense asset management suite.

The alarm will be reset if the Lifetime Indicator is not 0 days anymore (e.g. after connecting a new sensor or changing on the measurement conditions).

If the Lifetime Indicator is turned on, in the measuring mode the value will be automatically shown in the display on line 3.

Press [ENTER]




**Time to Maintenance:** This timer estimates when the next cleaning cycle should be performed to keep the best possible measurement performance. The timer is influenced by significant changes on the DLI parameters.

Time to Maintenance YES/NO  
Alarm YES/NO R# choose OC

The time to maintenance can be reset to the initial value by the menu "Reset ISM Counter/Timer" (see chapter 8.6.2 "Reset ISM Counter/Timer").

Press [ENTER]




Activation of the **Adaptive Calibration Timer:** This timer estimates when the next calibration should be performed to keep the best possible measurement performance. The timer is influenced by significant changes on the DLI parameters.

Adaptive Cal Timer YES/NO  
Alarm YES/NO R# choose OC

The Adaptive Calibration Timer will be reset to his initial value after a successful calibration. After a successful calibration will also be the alarm reset. If the Adaptive Cal Timer is turned on, the value will be automatically shown in the display on line 4.

Press [ENTER]



The initial value for Time to Maintenance as well as the Adaptive Calibration Timer can be modified according to the application experience and loaded down to the sensor.




**NOTE:** By connecting a sensor, the values for Time to Maintenance and/or Adaptive Calibration Timer are read out by the sensor.


Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values and return to the measurement display screen, while selecting Yes will save changes made.

## 8.6.2 Reset ISM Counter/Timer

This menu allows resetting counter and timer functions which cannot be reset automatically. The adaptive calibration timer will be reset after a successful adjustment or calibration.



Navigate to the menu "Reset ISM Counter/Timer" by using the ▲ and ▼ keys and press [ENTER].



If an pH sensor is connected, the menu for resetting the Time To Maintenance is displayed. Time To Maintenance needs to be reset after the following operations.

pH sensors: manual maintenance cycle on the sensor.


[Press ENTER]

### 8.6.3 DLI Stress Adjustment (only for pH ISM sensors)


Through this menu the calculation of the diagnostic data DLI, TTM and ACT can be adapted to application requirements and/or experience.



**NOTE:** The function is only available for pH ISM sensors with corresponding firmware versions.



Navigate to the menu "DLI Stress Adjustment" by using the ▲ and ▼ keys and press [ENTER].



Adjust the Process Stress parameter based on the particular application and/or requirements

Low: DLI, TTM and ACT will be increased approximately 25% compared with "Medium".


Medium: Default value, (equal DLI, TTM and ACT values based on former firmware versions of the transmitter).

High: DLI, TTM and ACT will be reduced approximately 25% compared with "Medium".

Pressing the [ENTER] key will bring up the Save Changes dialog. Selecting No will discard the entered values, while selecting Yes will make activate entered values.

## 8.7 Display

(PATH: Menu/Configure/Display)



Enter configuration mode as described in Section 8.1 "Enter Configuration Mode".

This menu allows for the configuration of the values to be displayed and also the configuration of the display itself.


### 8.7.1 Measurement

The display has 4 lines. Line 1 on top and Line 4 on the bottom.



Select the values (Measurement a, b, c or d) to be displayed on each line of the display.

The selection of the values for a, b, c, d needs to be done under Configuration/measurement/Channel Setup.




Select the "Error Display" mode. If this is set to "On" when an alarm or warning has occurred, the message "Failure – Press ENTER" will be displayed on Line 4 when an alarm occurs in the normal measurement mode.




Pressing the [ENTER] key again will bring up the Save Changes dialog. Selecting No will discard the entered values, while selecting Yes will make the entered values the current ones.

## 8.7.2 Resolution



This menu allows the setting of the resolution of each displayed value.


The accuracy of the measurement is not effected by this setting.



Possible settings are 1, 0.1, 0.01, 0.001 or Auto.

Pressing the [ENTER] key will bring up the Save Changes dialog.

## 8.7.3 Backlight



This Menu allows the setting of the back light options of the display.



Possible settings are On, On 50% or Auto Off 50%. If Auto Off 50% is selected then the backlight will go to 50% after 4 minutes with no keypad activity. The backlight will automatically come back on if a key is pressed.

Pressing the [ENTER] key will bring up the Save Changes dialog.

## 8.7.4 Name



This menu allows for the configuration of an alpha-numeric name which is displayed in the first 9 characters on lines 3 and 4 of the display. The default is nothing (blank).

If a name is entered on line 3 and/or 4 a measurement can be still displayed on the same line.




Use the ◀ and ▶ keys to navigate between digits to be altered. Using the ▲ and ▼ keys to change the character to be displayed. Once all digits of both display channels have been entered, press [ENTER] to bring up the Save Changes dialog.



The resulting display in the measurement mode appears on lines 3 and 4 ahead of the measurements.

## 8.7.5 ISM Sensor Monitoring (available when ISM sensor connected)




The sensor monitoring allows you to display the sensor monitoring details on line 3 and 4 in the display. The following options are possible:

Line 3 Off/Time Indicator/Time to Maint/Adapt Cal Timer  
Line 4 Off/Time Indicator/Time to Maint/Adapt Cal Timer

## 8.8 Hold Analog Outputs


(PATH: Menu/Configure/Hold Outputs)

Enter configuration mode as described in Section 8.1 "Enter Configuration Mode".



The "**Hold outputs**" function applies during the calibration process. If set "Hold outputs" to Yes, during calibration process the analog output, the output OC will be at hold state. The hold state depends on the setting. For the possible hold settings, see the list below. The following options are possible:

Hold Outputs? Yes/No



The "**DigitalIn**" function applies all the time. As soon as a signal is active on the digital input the transmitter goes to hold mode and the values on the analog output, the output OC will be at hold state.

DigitalIn1 / 2 State = Off/Low/High

**NOTE:** DigitalIn1 is to hold channel A (conventional sensor)  
DigitalIn2 is to hold channel B (ISM sensor)



Possible Hold states:

Output OC:	On/Off	(Configuration/Set point)
Analog Output:	Last/Fixed	(Configuration/Analog output)



## 9 System


(PATH: Menu/System)




While in measurement mode press the ◀ key. Press the ▼ or ▲ key to navigate to “System” – Menu and press [ENTER].

### 9.1 Set Language

(PATH: Menu/System/Set Language)



This menu allows the configuration of the display language.




The following selections are possible:

English, French, German, Italian, Spanish, Portuguese, Russian or Japanese (Katakana).


Pressing the [ENTER] key will bring up the Save Changes dialog.

### 9.2 Passwords

(PATH: Menu/System/Passwords)



This menu allows for the configuration of operator and administrator passwords, as well as setting up a list of allowed menus for the operator. The administrator has rights to access all menus. All default passwords for new transmitters are “00000”.



The passwords menu is protected: Enter the administrator password to enter the menu.

## 9.2.1 Changing Passwords

See Section 9.3 on how to enter the passwords menu. Select Change Administrator or Change Operator and set the new password.

```
A 0.28 μS/cm
A 25.00 °C
Change Administrator
New Password = 00000 ▲
```

Press the [ENTER] key and confirm the new password. Press [ENTER] again to bring up the Save Changed dialog.

```
A 0.28 μS/cm
A 25.00 °C
Re-enter password
New Password = 00000 ▲
```

## 9.2.2 Configuring Menu Access for Operator

See 9.3 on how to enter the passwords Menu. Select Configure Operator to configure the access list for the operator. It is possible to assign/deny rights to the following menus: Cal Key, Quick Setup, Configuration, System, PID Setup and Service.

```
A 0.28 μS/cm
A 25.00 °C
Enter Password 00000
Configure Operator ▲
```

Choose either Yes or No to give/deny access to the above menus and press [ENTER] to advance to the next items. Pressing the [ENTER] key after configuring all menus will bring up the Save Changes dialog. Selecting No will discard the entered values, while selecting Yes will make the entered values the current ones.

```
A 0.28 μS/cm
A 25.00 °C
Cal Key Yes
Quick Setup Yes ▲
```

## 9.3 Set/Clear Lockout

(PATH: Menu/System/Set/Clear Lockout)

This menu enables/disables the lockout functionality of the transmitter. The user will be asked for a password before being allowed into any menus if the lockout functionality is enabled.

```
A 0.28 μS/cm
A 25.00 °C
System
Set/Clear Lockout ▲
```

The lockout-menu is protected: Enter the administrator or operator password and select YES to enable or NO to disable the lockout functionality. Pressing the [ENTER] key after the selection will bring up the Save Changes dialog. Selecting No will discard the entered value, while selecting Yes will make the entered value the current one.

```
A 0.28 μS/cm
A 25.00 °C
Password = 00000
Enable Lockout = Yes ▲
```

## 9.4 Reset

(PATH: Menu/System/Reset)


This menu allows access to the following options:

Reset System, Reset Meter Cal, Reset Analog Cal.


```
A 0.28 μS/cm
A 25.00 °C
System
Reset ▲
```



### 9.4.1 Reset System




This menu allows the reset of the meter to the factory default settings (setpoints off, analog outputs off, etc.). The meter calibration and the analog output calibration are not affected.




Pressing the [ENTER] key after the selection will bring up a confirmation screen. Selecting No will return the user to the measurement mode with no changes, while selecting Yes will reset the meter.

### 9.4.2 Reset Meter Calibration




This menu allows the reset of the meter's calibration factors to the last factory calibration values.




Pressing the [ENTER] key after the selection will bring up a confirmation screen. Selecting No will return the user to the measurement mode with no changes, while selecting Yes will reset the meter calibration factors.

### 9.4.3 Reset Analog Calibration




This menu allows reset of the analog output calibration factors to the last factory calibration values.



Pressing the [ENTER] key after the selection will bring up a confirmation screen. Selecting No will return the user to the measurement mode with no changes, while selecting Yes will reset the analog output calibration.

## 9.5 Set Date & Time




Please enter the actual date and time. The following options are possible. This function is automatically activated at every power-up.

Date (YY-MM-DD):

Time (HH:MM:SS):

## 10 Service

(PATH: Menu/Service)



```

A 0.28 μS/cm
A 25.00 °C
MENU
Service ▲
  
```

While in measurement mode press the ◀ key. Press the ▲ or ▼ key to navigate to the “Service” menu and press [ENTER]. The available system configuration options are detailed below.

### 10.1 Diagnostics

(PATH: Menu/Service/Diagnostics)

```

A 0.28 μS/cm
A 25.00 °C
Service
Diagnostics ▲
  
```

This menu is a valuable tool for troubleshooting and provides diagnostic functionality for the following items: Model/Software Revision, Digital Input, Display, Keypad, Memory, Set OC, Read OC, Set Analog Outputs, Read Analog Outputs.

#### 10.1.1 Model/Software Revision

```

A 0.28 μS/cm
A 25.00 °C
Diagnostics
Model/Software Revision▲
  
```

Essential information for every Service call is the model and software revision number. This menu shows the part number, model and the serial number of the transmitter. By using the ▼ key it is possible to navigate forward through this menu and get additional information like the current version of firmware implemented on the transmitter: (Master V\_XXXX and Comm V\_XXXX); and – if an ISM sensor is connected – the version of the sensor firmware (Sensor FW V\_XXX) and sensor hardware (Sensor HW XXXX).

```

A 0.28 μS/cm
A 25.00 °C
PN xxxxxxxx Vx.xx
SN xxxxxxxxxx ▲
  
```

Press [ENTER] to exit from this display.

#### 10.1.2 Digital Input

```


A 0.28 μS/cm
A 25.00 °C
Diagnostics
Digital Input ▲
  
```

The digital input menu shows the state of the digital inputs. Press [ENTER] to exit from this display.

```


A 0.28 μS/cm
A 25.00 °C
Digital Input 1 = 0
Digital Input 2 = 0 ▲
  
```

### 10.1.3 Display




All pixels of the display will be lit for 15 seconds to allow troubleshooting of the display. After 15 seconds the transmitter will return to the normal measuring mode or press [ENTER] to exit sooner.


### 10.1.4 Keypad




For keypad diagnostics, the display will indicate which key is pressed. Pressing [ENTER] will return the transmitter to the normal measuring mode.




### 10.1.5 Memory



If Memory is selected then the transmitter will perform a RAM and ROM memory test. Test patterns will be written to and read from all RAM memory locations. The ROM checksum will be recalculated and compared to the value stored in the ROM.




### 10.1.6 Set OC



The Set OC diagnostic menu allows to open or close each OC manually. To access OC and 6, press [ENTER].

0 = open the OC  
1 = close the OC



Press [ENTER] to return to Measurement mode.

### 10.1.7 Read OC

```

A 0.28 µS/cm
A 25.00 °C
Diagnostics
Read Relays ▲
  
```

The Read OC diagnostic menu shows the state of each OC as defined below.  
To display OC 5 and 6, press [ENTER]. Press [ENTER] again to exit from this display.

0 = Normal  
1 = Inverted.

```

A 0.28 µS/cm
A 25.00 °C
Relay1 = 0 Relay2 = 0
Relay3 = 0 Relay4 = 0
  
```

### 10.1.8 Set Analog Outputs

```

A 0.28 µS/cm
A 25.00 °C
Diagnostics
Set Analog Outputs ▲
  
```

This menu enables the user to set all analog outputs to any mA value within the 0–22 mA range. Press [ENTER] to exit from this display.

```

A 0.28 µS/cm
A 25.00 °C
Analog out1 = 04.0 mA
Analog out2 = 04.0 mA ▲
  
```

### 10.1.9 Read Analog Outputs

```

A 0.28 µS/cm
A 25.00 °C
Diagnostics
Read Analog Outputs ▲
  
```

This menu shows the mA value of the analog outputs.

```

A 0.28 µS/cm
A 25.00 °C
Analog out1 = 20.5 mA
Analog out2 = 20.5 mA ▲
  
```

Press [ENTER] to exit from this display.

## 10.2 Calibrate

(PATH: Menu/Service/Calibrate)


```

A 0.28 µS/cm
A 25.00 °C
Service
Calibrate ▲
  
```

Enter Service Menu as described in section 11 “Enter Service Menu”, select Calibrate and press [ENTER].


This menu has the options to calibrate the transmitter and the analog outputs and also allows the unlocking of calibration functionality

## 10.2.1 Calibrate Meter (only for channel A)



The M400 transmitter is factory calibrated within specifications. It is not necessary to perform meter re-calibration unless extreme conditions cause an out of spec operation shown by Calibration Verification. Periodic verification/re-calibration may also be necessary to meet Q.A. requirements. Meter calibration can be selected as current (used for most dissolved oxygen, Voltage, Rg Diagnostic, Rr Diagnostic (used for pH), and temperature (used for all measurements).


### 10.2.1.1 Temperature




Temperature is performed as a three point calibration. The table above shows the resistance values of these three points.

Navigate to the Calibrate Meter screen and choose Temperature calibration for Channel A.

Press [ENTER] to begin temperature calibration process




The first text line will ask for the Point 1 temperature resistance value (this will correspond to temperature 1 value shown on the calibration module accessory). The second text line will show the measured resistance value. When the value stabilizes, press [ENTER] to perform calibration.




The transmitter screen will then prompt the user to enter the value for Point 2, and T2 will display the measured resistance value. When this value stabilizes, press [ENTER] to calibrate this range.

Repeat these steps for Point 3.




Press [ENTER] to bring up a confirmation screen. Select Yes to save the calibration values and the successful calibration is confirmed on the display.



The transmitter will return to the measurement mode in approximately 5 seconds.

### 10.2.1.2 Current



Current calibration is performed as a two point calibration.

Navigate to the Calibrate Meter screen and select Channel A.

```

A 0.28 μS/cm
A 25.00 °C
A Point1 = 0.0000 nA
A I = 0.0248 nA ▲

```

Enter the value for Point 1, in milliamps, of the current source connected to the input. The second display line will show the measured current. Press [ENTER] to begin the calibration process.

```

A 0.28 μS/cm
A 25.00 °C
A Point2 = 675.00 nA
A I = 776.36 nA ▲

```

Enter the value for Point 2, in milliamps, of the current source connected to the input. The second display line shows the measured current.

```

A 0.28 μS/cm
A 25.00 °C
Save Calibration Yes
Press ENTER to Exit ▲

```

Pressing the [ENTER] key after entering Point 2 will bring up a confirmation screen. Select Yes to save the calibration values and the successful calibration is confirmed on the display. The transmitter will return to the measurement mode in approximately 5 seconds.

### 10.2.1.3 Voltage

```

A 0.28 μS/cm
A 25.00 °C
Calibrate Meter
Channel A Voltage ▲

```

Voltage calibration is performed as a two point calibration.

Navigate to the Calibrate Meter screen and select Channel A and Voltage.

```

A 0.28 μS/cm
A 25.00 °C
A Point1 = -1.500 V
A V = -0.000 V ▲

```

Enter the value for Point 1 in, volts, connected to the input. The second display line will show the measured voltage. Press[ENTER] to begin the calibration process.

```

A 0.28 μS/cm
A 25.00 °C
A Point2 = 1.5000 V
A V = 0.1231 V ▲

```

Enter the value for Point 2, in volts, of the source connected to the input. The second display line shows the measured voltage.

```

A 0.28 μS/cm
A 25.00 °C
Save Calibration Yes
Press ENTER to Exit ▲

```

Pressing the [ENTER] key after entering Point 2 will bring up a confirmation screen. Select Yes to save the calibration values and the successful Calibration is confirmed on the display. The transmitter will return to the measurement mode in approximately 5 seconds.


### 10.2.1.4 Rg Diagnostic

```


A 0.28 μS/cm
A 25.00 °C
Calibrate Meter
Channel A Rg Diagnostic▲

```


Rg diagnostic is performed as a two point calibration. Navigate to the Calibrate Meter screen and select Channel A and Rg Diagnostic.



Enter the value for Point 1 of the calibration according to the resistor connected across the pH glass electrode measuring input. Press [ENTER] to begin the calibration process.




Enter the value for Point 2 of the calibration according to the resistor connected across the pH glass electrode measuring input.




Pressing the [ENTER] key after entering Point 2 will bring up a confirmation screen. Select Yes to save the calibration values and the successful calibration is confirmed on the display. The transmitter will return to the measurement mode in approximately 5 seconds.


### 10.2.1.5 Rr Diagnostic




Rr diagnostic is performed as a two point calibration. Navigate to the Calibrate Meter screen and select Channel A and Rr Diagnostic.



Enter the value for Point 1 of the calibration according to the resistor connected across the pH reference measuring input. Press [ENTER] to begin the calibration process.




Enter the value for Point 2 of the calibration according to the resistor connected across the pH reference measuring input.



Pressing the [ENTER] key after entering Point 2 will bring up a confirmation screen. Select Yes to save the calibration values and the successful calibration is confirmed on the display. The transmitter will return to the measurement mode in approximately 5 seconds.

### 10.2.1.6 Calibrate Analog Output Signals



Select the Analog Output you wish to calibrate. Each analog output can be calibrated at 4 and 20 mA.

```

A 0.28 µS/cm
A 25.00 °C
Aout1 20mA Set 45000
Press ENTER when Done ▲

```

Connect an accurate milliamp meter to the analog output terminals and then adjust the five digit number in the display until the milliamp meter reads 4.00 mA and repeat for 20.00 mA.

```

A 0.28 µS/cm
A 25.00 °C
Aout1 4mA Set 08800
Press ENTER when Done ▲

```

As the five digit number is increased the output current increases and as the number is decreased the output current decreases. Thus coarse changes in the output current can be made by changing the thousands or hundreds digits and fine changes can be made by changing the tens or ones digits.

```

A 0.28 µS/cm
A 25.00 °C
Save Calibration Yes
Press ENTER to Exit ▲

```

Pressing the [ENTER] key after entering both values will bring up a confirmation screen. Selecting No will discard the entered values, while selecting Yes will make the entered values the current ones.

## 10.2.2 Calibrate Unlock

```

A 0.28 µS/cm
A 25.00 °C
Calibrate Unlock

```

Select this Menu to configure the CAL Menu, see Section 7.

```

A 0.28 µS/cm
A 25.00 °C
Unlock Calibration Yes
Press ENTER to Continue▲

```

Selecting Yes means that meter and analog output calibration menus will be selectable under the CAL Menu. Selecting No means that only the sensor calibration is available under the CAL Menu. Press [ENTER] after the selection to display a confirmation screen.

## 10.3 Tech Service

(PATH: Menu/Tech Service)




**NOTE:** This menu is for METTLER TOLEDO service personnel use only.




## 11 Info

(PATH: Info)




\* Only available in combination with ISM sensors



Pressing the ▼ key will display the Info menu with the options Messages, Calibration Data and Model/Software Revision.

### 11.1 Messages

(PATH: Info/Messages)



The most recent message is displayed. The up and down arrow keys allow scrolling through the last four messages that have occurred.




Clear Messages clears all the messages. Messages are added to the message list when the condition that generates the message first occurs. If all messages are cleared and a message condition still exists and started before the clear then it will not appear in the list. For this message to re-occur in the list the condition must go away and then reappear.


Press [ENTER] to exit from this display.

### 11.2 Calibration Data

(PATH: Info/Calibration Data)



Selecting Calibration Data displays the calibration constants for each sensor.




P = calibration constants for the primary measurement  
S = calibration constants for the secondary measurement

Press ▼ for ORP calibration data of ISM pH sensors.

Press [ENTER] to exit from this display.


### 11.3 Model/Software Revision

(PATH: Info/Model/Software Revision)



Selecting Model/Software Revision will display the part number, model and the serial number of the transmitter.


By using the ▼ key it is possible to navigate forward through this menu and get additional information like the current version of firmware implemented on the transmitter (Master V\_XXXX and Comm V\_XXXX) and – if an ISM sensor is connected – the version of the sensor firmware (Sensor FW V\_XXX) and sensor hardware (Sensor HW XXXX).



The displayed information is important for any Service call.  
Press [ENTER] to exit from this display.


### 11.4 ISM Sensor Info (available when ISM sensor connected)

(PATH: Info/ISM Sensor Info)



After plugging in an ISM sensor it is possible by using the key A or ▼ to navigate to the Menu "ISM Sensor Info".

Press [ENTER] to select the menu.




The following information about the sensor will be shown in this menu. Use up and down arrows to scroll in the menu.

Type: Type of sensor (e.g. InPro 3250)  
Cal Date: Date of the last adjustment  
Serial-No.: Serial number of the connected sensor  
Part-No.: Part number of the connected sensor

Press [ENTER] to exit from this display.

### 11.5 ISM Sensor Diagnostics (available when ISM sensor connected)



(PATH: Info/ISM Diagnostics)



After plugging in an ISM sensor it is possible by using the key A or ▼ to navigate to the Menu "ISM Diagnostics".

Press [ENTER] to select the menu.

Navigate to one of the menus, described in this section, and press [ENTER] again.



### Cal History

The calibration history is stored with a time stamp in the ISM sensor and is displayed on the transmitter. The calibration history offers the following information:

**Fact** (Factory calibration: This is the original dataset, determined in the factory. This dataset remains stored in the sensor for reference and cannot be overwritten.

**Act** (Actual adjustment: This is the actual calibration dataset which is used for the measurement. This dataset moves to Cal2 position after the next adjustment.

**1. Adj** (First adjustment: This is the first adjustment after the factory calibration. This dataset remains stored in the sensor for reference and cannot be overwritten

**Cal1** (last calibration/adjustment: This is the last executed calibration/adjustment. This dataset moves to Cal2 and then to Cal3 when a new calibration/adjustment is performed. Afterwards, the dataset is not available anymore.

Cal2 and Cal3 acting in the same way as Cal1.

Definition:

**Adjustment:** The calibration procedure is completed and the calibration values are taken over and used for the measurement (Act and stated in Cal1. The current values from Act will move to Cal2.

**Calibration:** The calibration procedure is completed, but the calibration values will not be over-taken and the measurement continuous with the last valid adjustment dataset (Act. The dataset will be stored under Cal1.



The calibration history is used for the estimation of the lifetime indicator for ISM sensors.

Press [ENTER] to exit from this display.

**NOTE:** This function requires the correct setting of date and time during calibration and/or adjustment tasks (see chapter 9.5 "Set Date & Time").


### Sensor monitoring (not available for Cond 4-e sensor)

The sensor monitoring shows the different diagnostics functions available for each ISM sensor. The following information is available:




**Lifetime Indicator:** Shows an estimation of the remaining lifetime to ensure a reliable measurement. The lifetime is indicated in days (d) and percentage (%). For a description of the Lifetime indicator, please see section 8.6 "ISM Setup". For oxygen sensors, the lifetime indicator is related to the inner-body of the sensor. If you want to bring the bar indicator on the screen, see chapter 8.7.5 "ISM sensor monitoring" to activate ISM functions.

**Adaptive Cal Timer:** This timer shows when the next calibration should be performed to keep the best possible measurement performance. The Adaptive Cal Timer is indicated in days (d) and percentage (%). For a description of the Adaptive Cal Timer, please see section 8.6 "ISM Setup".



**Time to Maintenance:** This timer shows when the next cleaning cycle should be performed to keep the best possible measurement performance. The Time to Maintenance is indicated in days (d) and percentage (%). For a description of the Time to Maintenance, please see section 8.6 "ISM Setup". For oxygen sensors, the Time to Maintenance indicates a maintenance cycle for the membrane and electrolyte.

Press [ENTER] to exit from this display.



### Max. Temperature

The maximum temperature shows the maximum that this sensor has recorded, together with a time stamp of this maximum. This value is stored on the sensor and cannot be changed. During autoclaving the Max temperature is not recorded.

Max. Temperature

Tmax XXX°CYY/MM/DD

Press [ENTER] to exit from this display.



**NOTE:** This function requires the correct setting of date and time of the transmitter (see chapter 9.6 "Set Date & Time").

## **12 Maintenance**

### **12.1 Front Panel Cleaning**

Clean the front panel with a damp soft cloth (water only, no solvents). Gently wipe the surface and dry with a soft cloth.

## 13 Troubleshooting

If the equipment is used in a manner not specified by METTLER TOLEDO the protection provided by the equipment may be impaired. Review the table below for possible causes of common problems:

Problem	Possible Cause
Display is blank.	<ul style="list-style-type: none"> <li>– No power to M400/2XH Type 1.</li> <li>– LC display contrast set incorrectly.</li> <li>– Hardware failure.</li> </ul>
Incorrect measurement readings.	<ul style="list-style-type: none"> <li>– Sensor improperly installed.</li> <li>– Incorrect units multiplier entered.</li> <li>– Temperature compensation incorrectly set or disabled.</li> <li>– Sensor or transmitter needs calibration.</li> <li>– Sensor or patch cord defective or exceeds recommended maximum length.</li> <li>– Hardware failure.</li> </ul>
Measurement readings not stable.	<ul style="list-style-type: none"> <li>– Sensors or cables installed too close to equipment that generates high level of electrical noise.</li> <li>– Recommended cable length exceeded.</li> <li>– Averaging set too low.</li> <li>– Sensor or patch cord defective.</li> </ul>
Displayed $\Delta$ is flashing.	<ul style="list-style-type: none"> <li>– Setpoint is in alarm condition (setpoint exceeded).</li> <li>– Alarm has been selected (see chapter 8.5.1 "Alarm") and occurred.</li> </ul>
Cannot change menu settings.	<ul style="list-style-type: none"> <li>– User locked out for security reasons.</li> </ul>

### 13.1 Cond (resistive) Error Messages/ Warning- and Alarm List for Analog Sensors

Alarms	Description
Watchdog time-out*	SW/System fault
Cond Cell open*	Cell running dry (no measurement solution) or wires are broken
Cond Cell shorted*	Short circuit caused by sensor or cable

\* According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";  
PATH: Menu/Configure/Alarm/Clean/Setup Alarm)

## 13.2 pH Error Messages/Warning- and Alarm List

### 13.2.1 pH Sensors except Dual Membrane pH Electrodes

Warnings	Description
Warning pH slope >102%	Slope too big
Warning pH Slope <90%	Slope too small
Warning pH Zero $\pm 0.5$ pH	Out of range
Warning pHGs change <0.3**	Glass electrode resistance changed by more than factor 0.3
Warning pHGs change >3**	Glass electrode resistance changed by more than factor 3
Warning pHRef change <0.3**	Reference electrode resistance changed by more than factor 0.3
Warning pHRef change >3**	Reference electrode resistance changed by more than factor 3

Alarms	Description
Watchdog time-out*	SW/System fault
Error pH Slope >103%	Slope too big
Error pH Slope <80%	Slope too small
Error pH Zero $\pm 1.0$ pH	Out of range
Error pH Ref Res >150 K $\Omega$ **	Reference electrode resistance too big (break)
Error pH Ref Res <2000 $\Omega$ **	Reference electrode resistance too small (short)
Error pH GIs Res >2000 M $\Omega$ **	Glass electrode resistance too big (break)
Error pH GIs Res <5 M $\Omega$ **	Glass electrode resistance too small (short)

\* ISM sensors only

\*\* According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";  
PATH: Menu/Configure/Alarm/Clean/Setup Alarm)

### 13.2.2 Dual Membrane pH Electrodes (pH/pNa)

Warnings	Description
Warning pH slope >102%	Slope too big
Warning pH Slope < 90%	Slope too small
Warning pH Zero $\pm 0.5$ pH	Out of range
Warning pHGs change < 0.3*	Glass electrode resistance changed by more than factor 0.3
Warning pHGs change > 3*	Glass electrode resistance changed by more than factor 3
Warning pNaGs change < 0.3*	Glass electrode resistance changed by more than factor 0.3
Warning pNaGs change > 3*	Reference electrode resistance changed by more than factor 3

Alarms	Description
Watchdog time-out	SW/System fault
Error pH Slope >103%	Slope too big
Error pH Slope < 80%	Slope too small
Error pH Zero $\pm 1.0$ pH	Out of range
Error pNa Gls Res > 2000 M $\Omega$ *	Glass electrode resistance too big (break)
Error pNa Gls Res < 5 M $\Omega$ *	Glass electrode resistance too small (short)
Error pH Gls Res > 2000 M $\Omega$ *	Glass electrode resistance too big (break)
Error pH Gls Res < 5 M $\Omega$ *	Glass electrode resistance too small (short)

\* According to the parameterization of the transmitter (see chapter 8.5.1 "Alarm";  
PATH: Menu/Configure/Alarm/Clean/Setup Alarm)

### 13.2.3 ORP Messages

Warnings*	Description
Warning ORP ZeroPt > 30 mV	Zero offset too big
Warning ORP ZeroPt < -30 mV	Zero offset too small

Alarms*	Description
Watchdog time-out	SW/System fault
Error ORP ZeroPt > 60 mV	Zero offset too big
Error ORP ZeroPt < -60 mV	Zero offset too small

\* ISM sensors only



## 13.3 Warning- and Alarm Indication on the Display

### 13.3.1 Warning Indication

If there are conditions, which generate a warning, the message will be recorded and can be selected through the menu Messages (PATH: Info / Messages; see also chapter 12.1 "Messages"). According to the configuration of the transmitter the hint "Failure – Press ENTER" will be shown at line 4 of the display, if a warning or alarm has occurred (see also chapter 8.7 "Display"; PATH: Menu/Configure/Display/Measurement).

### 13.3.2 Alarm Indication

Alarms will be shown in the display by a flashing symbol  $\Delta$  and recorded through the menu point Messages (PATH: Info/Messages; see also chapter 12.1 "Messages").

Furthermore the detection of some alarms can be activated or deactivated (see chapter 8.5 "Alarm/Clean"; PATH: Menu/Configure/Alarm/Clean) for an indication on the display. If one of these alarms occurs and the detection has been activated, the flashing symbol  $\Delta$  will be shown on the display and the message will be recorded through the menu Messages (see chapter 12.1 "Messages"; PATH: Info / Messages).

Alarms which are caused by a violation of the limitation of a setpoint or the range (see chapter 8.4 "Setpoints"; PATH: Menu/Configure/Setpoint) will also be shown by a flashing symbol  $\Delta$  and recorded through the menu Messages (PATH: Info/Messages; see also chapter 12.1 "Messages").

According to the parameterization of the transmitter the hint "Failure – Press ENTER" will be shown at line 4 of the display, if a warning or alarm has occurred (see also chapter 8.7 "Display"; PATH: Menu/Configure/Display/Measurement).

## 14 Accessories and Spare Parts

Please contact your local METTLER TOLEDO sales office or representative for details for Additional accessories and spare parts.

<b>Description</b>	<b>Order no.</b>
Pipe Mount Kit for ½ DIN models	52 500 212
Panel Mount Kit for ½ DIN models	52 500 213
Protective Hood for ½ DIN models	52 500 214

## 15 Specifications

### 15.1 General Specifications

#### Conductivity 4-e

Measurement parameters	Conductivity/resistivity and temperature
Conductivity ranges 4-electrode sensor	20 $\mu$ S/cm to 650 mS/cm
Display range for 4-e sensor	20 $\mu$ S/cm to 650 mS/cm
Chemical concentration curves	<ul style="list-style-type: none"> <li>– NaCl: 0–26% @ 0 °C to 0–28% @ +100 °C</li> <li>– NaOH: 0–12% @ 0 °C to 0–16% @ +40 °C to 0–6% @ +100 °C</li> <li>– HCl: 0–18% @ –20 °C to 0–18% @ 0 °C to 0–5% @ +50 °C</li> <li>– HNO<sub>3</sub>: 0–30% @ –20 °C to 0–30% @ 0 °C to 0–8% @ +50 °C</li> <li>– H<sub>2</sub>SO<sub>4</sub>: 0–26% @ –12 °C to 0–26% @ +5 °C to 0–9% @ +100 °C</li> <li>– H<sub>3</sub>PO<sub>4</sub>: 0–35% @ +5 °C to +80 °C</li> <li>– User-defined concentration table (5 x 5 matrix)</li> </ul>
TDS ranges	NaCl, CaCO <sub>3</sub>
Cond/Res accuracy	$\pm$ 0.5 % of reading or 0.25 $\Omega$ , whichever is greater, up to 10 M $\Omega$ -cm
Cond/Res repeatability	$\pm$ 0.25% of reading or 0.25 $\Omega$ , whichever is greater
Cond/Res resolution	Auto/0.001/0.01/0.1/1 (can be selected)
Temperature input	Pt1000/Pt100/NTC22K
Temperature measuring range	–40 to +200 °C (–40 to +392 °F)
Temperature resolution	Auto/0.001/0.01/0.1/1 (can be selected)
Temperature accuracy	$\pm$ 0.25 °C ( $\pm$ 32.5 °F) within –30 to +150 °C (–22 to +302 °F); $\pm$ 0.50 °C ( $\pm$ 32.9 °F) outside
Temperature repeatability	$\pm$ 0.13 °C ( $\pm$ 32.2 °F)
Max. sensor cable length	61 m (200 ft); with 4-e sensors: 15 m (50 ft)
Calibration	1-point, 2-point or process

**pH/ORP**

Measurement parameters	pH, mV and temperature
pH display range	-2.00 to +20.00 pH
pH resolution	Auto/0.001/0.01/0.1/1 (can be selected)
pH accuracy <sup>1)</sup>	Analog: $\pm 0.02$ pH
mV range	-1500 to +1500 mV
mV resolution	Auto/0.001/0.01/0.1/1 mV (can be selected)
mV accuracy <sup>1)</sup>	Analog: $\pm 1$ mV
Temperature input <sup>2)</sup>	Pt1000/Pt100/NTC30K
Temperature measuring range	-30 to 130 °C (-22 to 266 °F)
Temperature resolution	Auto/0.001/0.01/0.1/1 (can be selected)
Temperature accuracy <sup>1)</sup>	Analog: $\pm 0.25$ °C in the range of -10 to +150 °C ( $\pm 32.5$ °F in the range of +14 to +176 °F)
Temperature repeatability <sup>1)</sup>	$\pm 0.13$ °C ( $\pm 32.2$ °F)
Temperature compensation	Automatic/Manual
Max. sensor cable length	- Analog: 10 to 20 m (33 to 65 ft) depending on sensor - ISM: 80 m (260 ft)
Calibration	1-point (offset), 2-point (slope or offset) or process (offset)

1) ISM input signal causes no additional error.

2) Not required on ISM sensors

**Available Buffer Sets**

Standard buffers	MT-9 buffers, MT-10 buffers, NIST Technical Buffers, NIST Standard Buffers (DIN 19266:2000-01), JIS Z 8802 buffers, Hach buffers, CIBA (94) buffers, Merck Titrisols-Reidel Fixanals, WTW buffers
Dual membrane electrode pH buffers (pH/pNa)	Mettler-pH/pNa buffers (Na <sup>+</sup> 3.9M)

## 15.2 Electrical Specifications

### 15.2.1 General Electrical Specifications

Display	Backlit LCD, 4 lines
Running capacity	Approx. 4 days
Keypad	5 tactile feedback keys
Languages	8 (English, German, French, Italian, Spanish, Portuguese, Russian and Japanese)
Connection terminals	Spring cage terminals, appropriate for wire cross section 0.2 to 1.5 mm <sup>2</sup> (AWG 16 – 24)
Analog input	4 to 20 mA (for pressure compensation)

### 15.2.2 4 to 20 mA (with HART)

Supply voltage	14 to 30 V DC
Number of outputs (analog)	2
Current outputs	Loop current 4 ... 20 mA, galvanically isolated up to 60 V from input and from earth / ground, protected against wrong polarity, feeding voltage 14 to 30 V DC
Measurement error through analog outputs	< ±0.05 mA over 1 to 20 mA range
Analog output configuration	Linear
PID process controller	Pulse length, pulse frequency
Hold input /Alarm contact	Yes/Yes (alarm delay 0 to 999 s)
Digital outputs	2 open collector (OC), 30 V DC, 100 mA, 0.9 W
Digital input	2, galvanically isolated up to 60 V from output, analog input and ground/ earth with switching limits 0.00 V DC to 1.00 V DC inactive 2.30 V DC to 30.00 V DC active
Alarm output delay	0 to 999 s

## 15.3 Mechanical Specifications

Dimensions	Housing – Height x Width x Depth	144 x 144 x 116 mm (5.7 x 5.7 x 4.6 inch)
	Front bezel – Height x Width	150 x 150 mm (5.9 x 5.9 inch)
	Max. depth – panel mounted	87 mm (excludes plug-in connectors)
Weight		1.50 kg (3.3 lb)
Material		Aluminum die cast
Enclosure rating		IP 66/NEMA4X

## 15.4 Environmental Specifications

Storage temperature	–40 to +70 °C (–40 to +158 °F)
Ambient temperature operating range	–20 to +60 °C (–4 to +140 °F)
Relative humidity	0 to 95 % non-condensing
EMC	According to EN 61326-1 (general requirements) Emission: Class B, Immunity: Class A
Approvals and certificates	<ul style="list-style-type: none"> <li>– ATEX/IECEX Zone 1 Ex ib [ia Ga] IIC T4 Gb</li> <li>– ATEX/IECEX Zone 21 Ex ib [ia Da] IIIC T80°C Db IP66</li> <li>– cFMus Class I, Division 1, Groups A, B, C, D T4A</li> <li>– cFMus Class II, Division 1, Groups E, F, G</li> <li>– cFMus Class III</li> <li>– cFMus Class I, Zone 0, AEx ia IIC T4 Ga</li> <li>– NEPSI EX Zone</li> </ul>
CE mark	The measuring system is in conformity with the statutory requirements of the EC Directives. METTLER TOLEDO confirms successful testing of the device by affixing to it the CE mark.


## 15.5 Control Drawings

### 15.5.1 Installation, Maintenance and Inspection


1. Intrinsically Safe Apparatus can be a source of ignition if internal spacings are shorted or connections opened.
2. Although intrinsically safe circuits are inherently low energy, they may still present a shock hazard because of the operating voltage.
3. Refer to manufacturer's written instructions before working on associated apparatus.
4. Inspection should be performed periodically to ensure that intrinsic safety has not been compromised. Inspections should include reviewing for unauthorized modifications, corrosion, accidental damage, change of flammable materials and the effects of aging.
5. User replaceable parts of an intrinsically safe system should not be replaced with other than the manufacturer's direct equivalent.
6. Maintenance work may be performed on energized apparatus in hazardous areas subject to the conditions as follows:
  - Disconnection of, and removal or replacement of, items of electrical apparatus and cabling if such action will not result in shorting of different intrinsically safe circuits.
  - Adjustment of any control that is necessary for the calibration of the electrical apparatus or system.
  - Only test instruments specified in the written instructions should be used.
  - Performance of other maintenance activities specifically permitted by the relevant control drawing and instruction manual.
7. Maintenance of Associated Apparatus and parts of intrinsically safe circuits located in unclassified areas should be restricted to that described in a way such that electrical apparatus or parts of circuits remain interconnected with parts of intrinsically safe systems located in hazardous areas. Safety barrier ground connections should not be removed without first disconnecting the hazardous-area circuits.
8. Other maintenance work on Associated Apparatus or parts of an intrinsically safe circuit mounted in an unclassified area should be performed only if the electrical apparatus or part of a circuit is disconnected from the part of the circuit located in a hazardous area.
9. The location classification and the suitability of the intrinsically safe system for that classification should be verified. This includes verifying that the class, group and temperature ratings of both the Intrinsically Safe Apparatus and the Associated Apparatus agree with the actual classification of the location.

10. Prior to energizing, an intrinsically safe system should be inspected to ensure the following:
- Installation is in compliance with the documentation;
  - Intrinsically safe circuits are properly separated from non-intrinsically safe circuits;
  - Cable shields are grounded in accordance with the installation documentation;
  - Modifications have been authorized;
  - Cables and wiring are not damaged;
  - Bonding and grounding connections are tight;
  - Bonding and grounding hardware is not corroded;
  - Resistance of any grounding conductor, including termination resistance from shunt-type-Associated Apparatus to the grounding electrode does not exceed one ohm;
  - Protection has not been defeated by bypassing; and
  - Check for signs of corrosion on the equipment and connections.
11. All deficiencies should be corrected.

## 15.5.2 Control Installation Drawing General Installation








12112602 A

**Hazardous Classified Area  
Sensor Board  
belonging to  
M400 Multi-parameter Transmitters  
control drawing 12112601 or 12112603**

Sensor Interface	In type of protection intrinsic safety, only for connection to M400, with the following maximum values				
	U(V)	I(mA)	P(mW)	L(mH)	C(uF)
pH measuring loop, Terminal A,E,G	Uo=5.88	Io=1.3	Po=1.9	Lo=5	Co=2.1
Conductivity measuring loop, Terminal A,B,E,G	Uo=5.88	Io=29	Po=4.3	Lo=1	Co=2.5
DO measuring loop, Terminal B,C,D,H	Uo=5.88	Io=29	Po=4.3	Lo=1	Co=2.5
Temperature measuring loop, Terminal I,J,K	Uo=5.88	Io=5.4	Po=8	Lo=5	Co=2
One-wire measuring loop, Terminal L,M	Uo=5.88	Io=22	Po=32	Lo=1	Co=2.8
485 measuring loop, Terminal N,O	Uo=5.88 Ui=30V	Io=54 Ii=100	Po=80 Pi=0.8	Lo=1 Li=0	Co=1.9 Ci=0.7
Analog input measuring loop, Terminal P,Q	Ui=30	Ii=100	Pi=800	Li=0	Ci=0.015

The measuring circuits are galvanically connected.



**WARNING - SUBSTITUTION OF COMPONENTS MAY IMPAIR INTRINSIC SAFETY**  
**WARNING - SUBSTITUTION OF COMPONENTS MAY IMPAIR THE SUITABILITY FOR ZONE 2**

- Notes  
IECEX, ATEX, FM, CSA  
1. When installed in M400, Intrinsically Safe Equipment connecting to A-Q must be approved or be a Simple Apparatus.  
2. A Simple Apparatus is defined as a device that does not generates more than 1.5V, 0.1A or 25mW.  
3. Check out the maxm values for IS (intrinsically safe) in this page for use.

MarkNum	C.F. No.	Sign	Date	Pattern	Weight/Scale
Designer		Authorization		S	1:1
Check		Approval			
Technics		Date		1	Pages Page 1

Mettler-Toledo Instruments  
(Shanghai) Co. Ltd.

Control Drawing,  
Sensor, M400

12112602 A

### 15.5.3 Notes

1. The intrinsic safety entity concept allows the interconnection of FM Approved intrinsically safe devices with entity parameters not specifically examined in combination as a system when:  $V_{oc} (U_o)$  or  $V_t \leq V_{max}$ ,  $I_{sc} (I_o)$  or  $I_t \leq I_{max}$ ,  $C_a (C_o) \geq C_i + C_{cable}$ ,  $L_a (L_o) \geq L_i + L_{cable}$ ,  $P_o \leq P_i$
2. The intrinsic safety fieldbus intrinsically safe concept allows the interconnection of FM Approved intrinsically safe devices with fieldbus intrinsically safe concept parameters not specifically examined in combination as a system when:  $V_{oc} (U_o)$  or  $V_t < V_{max}$ ,  $I_{sc} (I_o)$  or  $I_t \leq I_{max}$ ,  $P_o \leq P_i$
3. The configuration of associated apparatus must be FM Approved under the entity concept.
4. Associated Apparatus manufacturer's installation drawing must be followed when installing this equipment.
5. The configuration of field device sensor must be FM Approved under the entity concept.
6. The installation must be in accordance with the National Electrical Code. (ANSI/NFPA 70 (NEC.)), Articles 504 and 505, and ANSI/ISA-RP12.06.01, or the Canadian Electrical (CE) Code. (CEC Part 1, CAN/CSA-C22.1), Appendix F, and ANSI/ISARP12.06.01 when installed in Canada.
7. A dust-tight conduit seal must be used when installed in Class II and Class III environments.
8. Control equipment connected to the associated apparatus must not use or generate more than the maximum unclassified location voltage,  $U_m$ , or 250 VAC/DC.
9. Resistance between intrinsically safe ground and earth ground must be less than one ohm.
10. For Class I, Zone 0 and Division 1 locations, installation of the Multi-parameter Transmitter M400/2XH Type 1 should be in accordance with ANSI/ISA RP12.06.01 "Installation of Intrinsically Safe Systems for Hazardous (Classified) Locations" and the National Electrical Code. (ANSI/ NRPA 70), or Canadian Electrical (CE) Code. (CEC Part 1, CAN/CSA-C22.1) when installed in Canada.
11. The Multi-parameter Transmitter M400/2XH Type 1 is FM Approved for Class I, Zone 0 and Division 1 applications. If connecting [AEx ib] or [Ex ib] associated apparatus to the Multiparameter Transmitter M400/2XH Type 1, the above system is only suitable for Class I, Zone 1, and is not suitable for Class I, Zone 0, or Division 1 hazardous (classified) locations.
12. For Division 2 installations, the associated apparatus is not required to be FM Approved under entity concept if the Multi-parameter Transmitter M400/2XH Type 1 is installed in accordance with the National Electrical Code. (ANSI/NFPA 70), Articles 504 and 505 or Canadian Electrical (CE) Code., CAN/CSA-C22.1, Part 1, Appendix F, for Division 2 wiring methods excluding nonincendive field wiring.
13.  $L_i$  may be greater than  $L_a$  and the cable length restrictions due to cable inductance ( $L_{cable}$ ) can be ignored if both the following conditions are met:  $L_a/R_a$  (or  $L_o/R_o$ )  $>$   $L_i/R_i$ ;  $L_a/R_a$  (or  $L_o/R_o$ )  $>$   $L_{cable}/R_{cable}$
14. If the electrical parameters of the cable used are unknown, the following values may be used: Capacitance - 197 pF/m (60 pF/ft.); Inductance - 0.66  $\mu$ H/m (0.20  $\mu$ H/ft.)
15. Simple apparatus is defined as a device that does not generate more than 1.5 V, 0.1 A, or 25 mW.
16. No revision to the control installation drawing without prior authorization by FM Approvals.

## 16 Default Table

### Common

Parameter	Sub parameter	Value	Unit
Alarm	OC	2	
	delay	1	
	hysteresis	0	
	state	inverted	
	Power failure	No	
	Software failure	No	
	ChB disconnected	Yes	
Clean	OC	1	
	Hold mode	Hold	
	interval	0	
	Clean time	0	
	delay	0	
	hysteresis	0	
	Hold outputs		Yes
Digital In		off	
Lockout		no	
ISM monitor	Lifetime indicator	Yes	Alarm Yes
	Time to maint	Yes	Alarm Yes
	Adapt Cal timer	Yes	Alarm Yes
	OC	None	
language		English	
Passwords	administrator	00000	
	operator	00000	
All OCs	delay	10	sec
	hysteresis	5	For measurement unit pH, mV, °C, the same unit. For the other measurement unit, it is %.
	state	normal	
	hold mode	Last Value	
All analog out	mode	4 – 20 mA	
	type	normal	
	alarm	22.0mA	
	hold mode	last value	
	Aout 1 Damping	1 sec	

**pH**

Parameter	Sub parameter	Value	Unit
Channel X	a	pH	pH
	b	temperature	°C
	c	None	
	d	None	
Temperature source (analog sensor)		Auto	
pH buffer		Mettler-9	
Drift Control		Auto	
IP		7.0 (ISM sensor reading from sensor)	pH
STC		0.000	pH/°C
Fix CalTemp		No	
Cal constants (for Analog sensor)	pH	S=100.0%,Z=7.000pH	
	temperature	M=1.0, A=0.0	
Cal constants (for ISM sensor)		Read from sensor	
Resolution	pH	0.01	pH
	Temperature	0.1	°C
Analog outputs	1	a	
	2	b	
pH	Value 4 mA	2	pH
	value 20 mA	12	pH
temperature	Value 4 mA	0	°C
	value 20 mA	100	°C
Set point 1	measurement	a	
	type	off	
	OC	None	
Set point 2	measurement	b	
	Type	off	
	OC	None	
Alarm	Rg diagnostics	Yes	
	Rr diagnostics	Yes	

**pH/pNa**

<b>Parameter</b>	<b>Sub parameter</b>	<b>Value</b>	<b>Unit</b>
Channel X	a	pH	pH
	b	temperature	°C
	c	None	
	d	None	
Temperature source (analog sensor)		Auto	
pH buffer		Na <sup>+</sup> 3.9M	
Drift Control		Auto	
IP		Reading from sensor	pH
STC		0.000	pH/°C
Fix CalTemp		No	
Cal constants		Read from sensor	
Resolution	pH	0.01	pH
	Temperature	0.1	°C
Analog outputs	1	a	
	2	b	
pH	Value 4 mA	2	pH
	value 20 mA	12	pH
temperature	Value 4 mA	0	°C
	value 20 mA	100	°C
Set point 1	measurement	a	
	type	off	
	OC	None	
Set point 2	measurement	b	
	Type	off	
	OC	None	
Alarm	Rg diagnostics	Yes	

## Resistivity/Conductivity

Parameter	Sub parameter	Value	Unit
Channel X	a	Resistivity	$\Omega$ -cm
	b	temperature	$^{\circ}$ C
	c	None	
	d	None	
Temperature source (analog sensor)		Auto	
Compensation		Standard	
Cal constants (for analog sensor)	Cond/Res	M=0.1, A=0.0	
	temperature	M=1.0, A=0.0	
Cal constants (for ISM sensor)		Read from sensor	
Resolution	Resistivity	0.01	$\Omega$ -cm
	Temperature	0.1	$^{\circ}$ C
Analog outputs	1	a	
	2	b	
Conductivity/Resistivity	Value 4 mA	10	M $\Omega$ -cm
	Value 20 mA	20	M $\Omega$ -cm
Temperature	value 4 mA	0	$^{\circ}$ C
	value 20 mA	100	$^{\circ}$ C
Set point 1	measurement	a	
	type	off	
	OC	None	
Set point 2	measurement	b	
	Type	off	
	OC	None	
Alarm	Cond cell shorted	No	
	Dry cond sensor	No	
	Cell deviation (ISM sensor)	No	

## 17 Warranty

METTLER TOLEDO warrants this product to be free from significant deviations in material and workmanship for a period of one year from the date of purchase. If repair is necessary and not the result of abuse or misuse within the warranty period, please return by freight pre-paid and amendment will be made without any charge. METTLER TOLEDO's Customer Service Dept. will determine if the product problem is due to deviations or customer abuse. Out-of-warranty products will be repaired on an exchange basis at cost.

The above warranty is the only warranty made by METTLER TOLEDO and is lieu of all other warranties, expressed or implied, including, without limitation, implied warranties of merchantability and fitness for a particular purpose. METTLER TOLEDO shall not be liable for any loss, claim, expense or damage caused by, contributed to or arising out of the acts or omissions of the Buyer or Third Parties, whether negligent or otherwise. In no event shall METTLER TOLEDO's liability for any cause of action whatsoever exceed the cost of the item giving rise to the claim, whether based in contract, warranty, indemnity or tort (including negligence).



## 18 Buffer Tables

M400 transmitters have the ability to do automatic pH buffer recognition. The following tables show different standard buffers that are automatically recognized.

### 18.1 Standard pH Buffers

#### 18.1.1 Mettler-9

Temp (°C)	pH of buffer solutions			
0	2.03	4.01	7.12	9.52
5	2.02	4.01	7.09	9.45
10	2.01	4.00	7.06	9.38
15	2.00	4.00	7.04	9.32
20	2.00	4.00	7.02	9.26
25	2.00	4.01	7.00	9.21
30	1.99	4.01	6.99	9.16
35	1.99	4.02	6.98	9.11
40	1.98	4.03	6.97	9.06
45	1.98	4.04	6.97	9.03
50	1.98	4.06	6.97	8.99
55	1.98	4.08	6.98	8.96
60	1.98	4.10	6.98	8.93
65	1.98	4.13	6.99	8.90
70	1.99	4.16	7.00	8.88
75	1.99	4.19	7.02	8.85
80	2.00	4.22	7.04	8.83
85	2.00	4.26	7.06	8.81
90	2.00	4.30	7.09	8.79
95	2.00	4.35	7.12	8.77

## 18.1.2 Mettler-10

Temp (°C)	pH of buffer solutions			
0	2.03	4.01	7.12	10.65
5	2.02	4.01	7.09	10.52
10	2.01	4.00	7.06	10.39
15	2.00	4.00	7.04	10.26
20	2.00	4.00	7.02	10.13
25	2.00	4.01	7.00	10.00
30	1.99	4.01	6.99	9.87
35	1.99	4.02	6.98	9.74
40	1.98	4.03	6.97	9.61
45	1.98	4.04	6.97	9.48
50	1.98	4.06	6.97	9.35
55	1.98	4.08	6.98	
60	1.98	4.10	6.98	
65	1.99	4.13	6.99	
70	1.98	4.16	7.00	
75	1.99	4.19	7.02	
80	2.00	4.22	7.04	
85	2.00	4.26	7.06	
90	2.00	4.30	7.09	
95	2.00	4.35	7.12	

## 18.1.3 NIST Technical Buffers

Temp (°C)	pH of buffer solutions				
0	1.67	4.00	7.115	10.32	13.42
5	1.67	4.00	7.085	10.25	13.21
10	1.67	4.00	7.06	10.18	13.01
15	1.67	4.00	7.04	10.12	12.80
20	1.675	4.00	7.015	10.07	12.64
25	1.68	4.005	7.00	10.01	12.46
30	1.68	4.015	6.985	9.97	12.30
35	1.69	4.025	6.98	9.93	12.13
40	1.69	4.03	6.975	9.89	11.99
45	1.70	4.045	6.975	9.86	11.84
50	1.705	4.06	6.97	9.83	11.71
55	1.715	4.075	6.97		11.57
60	1.72	4.085	6.97		11.45
65	1.73	4.10	6.98		
70	1.74	4.13	6.99		
75	1.75	4.14	7.01		
80	1.765	4.16	7.03		
85	1.78	4.18	7.05		
90	1.79	4.21	7.08		
95	1.805	4.23	7.11		

### 18.1.4 NIST Standard Buffers (DIN and JIS 19266: 2000–01)

Temp (°C)	pH of buffer solutions			
0				
5	1.668	4.004	6.950	9.392
10	1.670	4.001	6.922	9.331
15	1.672	4.001	6.900	9.277
20	1.676	4.003	6.880	9.228
25	1.680	4.008	6.865	9.184
30	1.685	4.015	6.853	9.144
37	1.694	4.028	6.841	9.095
40	1.697	4.036	6.837	9.076
45	1.704	4.049	6.834	9.046
50	1.712	4.064	6.833	9.018
55	1.715	4.075	6.834	8.985
60	1.723	4.091	6.836	8.962
70	1.743	4.126	6.845	8.921
80	1.766	4.164	6.859	8.885
90	1.792	4.205	6.877	8.850
95	1.806	4.227	6.886	8.833



**NOTE:** The pH(S) values of the individual charges of the secondary reference materials are documented in a certificate of an accredited laboratory. This certificate is supplied with the respective buffer materials. Only these pH(S) values shall be used as standard values for the secondary reference buffer materials. Correspondingly, this standard does not include a table with standard pH values for practical use. The table above only provides examples of pH(PS) values for orientation.

### 18.1.5 Hach Buffers

Buffer values up to 60 °C as specified by Bergmann & Beving Process AB.

Temp (°C)	pH of buffer solutions		
0	4.00	7.14	10.30
5	4.00	7.10	10.23
10	4.00	7.04	10.11
15	4.00	7.04	10.11
20	4.00	7.02	10.05
25	4.01	7.00	10.00
30	4.01	6.99	9.96
35	4.02	6.98	9.92
40	4.03	6.98	9.88
45	4.05	6.98	9.85
50	4.06	6.98	9.82
55	4.07	6.98	9.79
60	4.09	6.99	9.76

### 18.1.6 Ciba (94) Buffers

Temp (°C)	pH of buffer solutions				
0	2.04	4.00	7.10	10.30	
5	2.09	4.02	7.08	10.21	
10	2.07	4.00	7.05	10.14	
15	2.08	4.00	7.02	10.06	
20	2.09	4.01	6.98	9.99	
25	2.08	4.02	6.98	9.95	
30	2.06	4.00	6.96	9.89	
35	2.06	4.01	6.95	9.85	
40	2.07	4.02	6.94	9.81	
45	2.06	4.03	6.93	9.77	
50	2.06	4.04	6.93	9.73	
55	2.05	4.05	6.91	9.68	
60	2.08	4.10	6.93	9.66	
65	2.07*	4.10*	6.92*	9.61*	
70	2.07	4.11	6.92	9.57	
75	2.04*	4.13*	6.92*	9.54*	
80	2.02	4.15	6.93	9.52	
85	2.03*	4.17*	6.95*	9.47*	
90	2.04	4.20	6.97	9.43	
95	2.05*	4.22*	6.99*	9.38*	

\* Extrapolated

### 18.1.7 Merck Titrisole, Riedel-de-Haën Fixanale

Temp (°C)	pH of buffer solutions				
0	2.01	4.05	7.13	9.24	12.58
5	2.01	4.05	7.07	9.16	12.41
10	2.01	4.02	7.05	9.11	12.26
15	2.00	4.01	7.02	9.05	12.10
20	2.00	4.00	7.00	9.00	12.00
25	2.00	4.01	6.98	8.95	11.88
30	2.00	4.01	6.98	8.91	11.72
35	2.00	4.01	6.96	8.88	11.67
40	2.00	4.01	6.95	8.85	11.54
45	2.00	4.01	6.95	8.82	11.44
50	2.00	4.00	6.95	8.79	11.33
55	2.00	4.00	6.95	8.76	11.19
60	2.00	4.00	6.96	8.73	11.04
65	2.00	4.00	6.96	8.72	10.97
70	2.01	4.00	6.96	8.70	10.90
75	2.01	4.00	6.96	8.68	10.80
80	2.01	4.00	6.97	8.66	10.70
85	2.01	4.00	6.98	8.65	10.59
90	2.01	4.00	7.00	8.64	10.48
95	2.01	4.00	7.02	8.64	10.37

## 18.1.8 WTW Buffers

Temp (°C)	pH of buffer solutions			
0	2.03	4.01	7.12	10.65
5	2.02	4.01	7.09	10.52
10	2.01	4.00	7.06	10.39
15	2.00	4.00	7.04	10.26
20	2.00	4.00	7.02	10.13
25	2.00	4.01	7.00	10.00
30	1.99	4.01	6.99	9.87
35	1.99	4.02	6.98	9.74
40	1.98	4.03	6.97	9.61
45	1.98	4.04	6.97	9.48
50	1.98	4.06	6.97	9.35
55	1.98	4.08	6.98	
60	1.98	4.10	6.98	
65	1.99	4.13	6.99	
70		4.16	7.00	
75		4.19	7.02	
80		4.22	7.04	
85		4.26	7.06	
90		4.30	7.09	
95		4.35	7.12	

## 18.1.9 JIS Z 8802 Buffers

Temp (°C)	pH of buffer solutions			
0	1.666	4.003	6.984	9.464
5	1.668	3.999	6.951	9.395
10	1.670	3.998	6.923	9.332
15	1.672	3.999	6.900	9.276
20	1.675	4.002	6.881	9.225
25	1.679	4.008	6.865	9.180
30	1.683	4.015	6.853	9.139
35	1.688	4.024	6.844	9.102
38	1.691	4.030	6.840	9.081
40	1.694	4.035	6.838	9.068
45	1.700	4.047	6.834	9.038
50	1.707	4.060	6.833	9.011
55	1.715	4.075	6.834	8.985
60	1.723	4.091	6.836	8.962
70	1.743	4.126	6.845	8.921
80	1.766	4.164	6.859	8.885
90	1.792	4.205	6.877	8.850
95	1.806	4.227	6.886	8.833

## 18.2 Dual Membrane pH Electrode Buffers

### 18.2.1 Mettler-pH/pNa Buffers (Na<sup>+</sup> 3.9M)

Temp (°C)	pH of buffer solutions			
0	1.98	3.99	7.01	9.51
5	1.98	3.99	7.00	9.43
10	1.99	3.99	7.00	9.36
15	1.99	3.99	6.99	9.30
20	1.99	4.00	7.00	9.25
25	2.00	4.01	7.00	9.21
30	2.00	4.02	7.01	9.18
35	2.01	4.04	7.01	9.15
40	2.01	4.05	7.02	9.12
45	2.02	4.07	7.03	9.11
50	2.02	4.09	7.04	9.10



For addresses of METTLER TOLEDO  
Market Organizations, please go to:  
**[www.mt.com/contacts](http://www.mt.com/contacts)**

**METTLER TOLEDO Group**  
Process Analytics  
Local contact: [www.mt.com/contacts](http://www.mt.com/contacts)

Subject to technical changes  
© 11/2022 METTLER TOLEDO. All rights reserved  
30 584 062 B  
MarCom Urdorf, Switzerland

**[www.mt.com/pro](http://www.mt.com/pro)**

For more information



Management System  
certified according to  
ISO 9001/ISO 14001

